

- e. An elevator that serve all bedrooms if the number of floors is more than a ground floor and two floors.
- f. In hotels and motels, there should be a public lavatory for men and another one for women for the service of dinning rooms and a public lavatory for men and another one for women in the reception hall and the waiting hall or the mezzanine for the service of the reception hall and the waiting hall.
 - Each lavatory should have a sink, a seat toilet, a cover and a bidet where there is a door that separate between the sink and the toilet. In each lavatory, there should be cold and hot running water. If the dinning room is on the same floor as the reception hall, there can be one lavatory for men and another one for women for the service of the two halls providing that each lavatory should have two sinks, two toilets and two bidets where every toilet is separate from the two sinks and from the other toilets.
- g. In hotels, the limit inferior for the net area of the rooms without a bath and the hall of entrances should not be less than the following:

i. Single room: (9) square metersii. Double rooms: (11) square metersiii. A room for 3 people: (13) square meters

- h. Each bedroom should be supplemented with a bath which includes a shower or a bath tub with a handle and a shower, a seat toilet with a cover and a bidet, a sink, (cold and hot) running water and a socket for the electric shaver near the mirror.
- i. In motels , the limit inferior for the net area of the room without the bath and the hall of entrances should not be less than the following:

i. Single room: (8) square metersii. Double rooms: (10) square metersiii. A room for 3 people: (12) square meters

- j. In motels, the private or the mutual baths can include a shower or a bath tub with a shower, seat toilet with a cover and bidet, sink, cold and hot running water and a socket for the electric shaver near the mirror where the number of baths is not less than the following rates:
 - -(25%) of the rooms with independent baths related to them.
 - (75%) of the rooms with mutual baths where a bath is for every two rooms.
- k. In hotel apartments, the limit inferior for the area of the bedroom without the bath and the hall of entrances should be as the following:

i. Bedroom: (12) square metersii. Studio: (17) square meters

- I. In hotel apartments, there should be a bathroom with a shower or a bath tub with a handle, a sink, a seat toilet with a cover and a bidet, a socket for the electric shaver near the mirror as well as cold and hot running water.
- m. Sufficient lighting should be provided in the public entrance, the passages, the stairs, the rooms and the halls.
- n. Air-conditioning should be provided for all the rooms, the halls, the restaurants and the hall of entrances.