- L. Visually inspect all exposed pipe, fittings, valves and joints during the tests.
- M. Ensure that all valves in the pipeline are satisfactorily operating under working pressure.

## **END OF SECTION**

