- Figure 67. Standard section of a two-way street with Intermediate Island
- Figure 68. Example of flared sides' curb cut
- Figure 69. Example of returned curbs curb cut
- Figure 70. Example of curbs ramp extensions
- Figure 71. Example of depressed curb cut in a corner
- Figure 72. Incorrect solutions to provide access to garages
- **Figure 73.** Possible solution to provide access to garages
- Figure 74. Slight depression of sidewalk is only allowed when this is the only alternative
- Figure 75. Example of a raised pedestrian crossing
- Figure 76. Offset intermediate island
- Figure 77. Aligned intermediate island
- Figure 78. Example of accessible parking places with lateral aisle
- Figure 79. Example of an accessible parking place along the sidewalk with sign on post
- Figure 80. Example of an accessible garbage container
- **Figure 81.** Wherever possible terraces should be placed in the furniture zone of the sidewalk. When required part of the parking places can be integrated into the terrace
- **Figure 82.** Terrace exceptionally invading the walking path but protected by vegetal fence and leaving at least 2000 mm of free walk way
- Figure 83. Alternative path in the same sidewalk
- Figure 84. Alternative path in the opposite sidewalk
- Figure 85. Alternative path under the scaffolding frontal view
- Figure 86. Alternative path under the scaffolding plan
- **Figure 87.** Removable paths scheme connecting all beach services
- **Figure 88.** Orientation rope. Length will vary depending on water conditions
- Figure 89. Outdoor shower
- Figure 90. Example of ISO and ANSI magnetic warning signs
- Figure 91. Example of a commercial kiosk
- Figure 92. International Symbol of Access with directional arrow
- **Figure 93.** Direct access from parking area to building entrance
- Figure 94. Building entrance