Table 1-6: Coating Material Classifications

Significance of notations & Meanings

1. X = low build (nominal to 70µm DFT per coat)

Y = high build (>150µm DFT per coat)

- 2. amines and amides may also mean their adducts
- 3. zinc content of zinc rich primers shall mean at least 90% zinc : 10% binder in the dry film. Other components shall not exceed 5% in the dry film.
- A. Primers (X only)
 - 1. micaceous iron oxide (two pack)
 - 2. zinc phosphate epoxy (two pack)
 - 3. zinc chromate epoxy (two pack)
 - 4. zinc rich epoxy (50% zinc)
 - 5. zinc rich epoxy (90% zinc)
 - 6. zinc silicate (90% zinc)
- B. Solvent based single pack (X or Y)
 - 1. Chlorinated rubber
 - 2. Bituminous
 - 3. Vinyl
 - 4. moisture cure epoxy (X only)
 - 5. moisture cure urethane (X only)
 - 6. self polishing copolymer antifouling (X only)
- C. Solvent based two pack (X or Y)
 - 1. epoxy aromatic amine
 - 2. epoxy aliphatic amine
 - 3. epoxy cycloaliphate amine
 - 4. epoxy polyamide