Vertical gap not to exceed 15 mm.

"Mind the Gap" sign on the platform at all door entrances and on train doors.

10.2.12. Emergency and evacuation

Emergency and evacuation information shall be provided in audio and visuals format in real time.

Staff training and drills shall be provided for emergency and evacuation situations to assist persons with mobility and sensory impairments.