12.3.2 Preparation

A. Prepare and protect adjacent work from damage

12.3.3 Cleaning

- A. Clean concrete surfaces of dirt or other contamination; wire brush using water, rinse surface and allow drying.
- B. Flush out cracks and voids with compressed air and water to remove laitance and dirt.
- C. High Pressure compressed air cleaning: Apply pressure to contaminated surfaces.

12.3.4 Field Quality Control

- A. Section 01400 Quality Control.
- B. Test concrete for calcium chloride content during the execution of the Work.

12.3.5 Schedule

A. Provide a work schedule by location and work activity

END OF SECTION