All equipment shall be fit for use for the purposes specified or implied.

1.2.3 Protective Clothing

- Overalls
- 2. Martindale masks, carbon filter masks
- 3. Air respirators
- 4. Protective goggles
- 5. Gloves, head covers
- 6. Blasting protective gear
- 7. Protective boots.

1.2.4 Health and Safety

A. Provision under Section 01540 shall be followed. Health and safety training shall be provided to the staff.

1.2.5 Fastenings

- A. Bolts, nuts and washers and other demountable fastenings of shall be mild steel galvanised or stainless steel to BS970: Part 4 Grade 316S16. PTFE washers and isolators shall be used when fitting, fastening or bolting dissimilar metals.
- B. Fastenings of ferrous parts except high tensile shall be galvanised to BS EN ISO 1461 or sherardised to BS4921. They shall be primed and painted according to Table1-1.
- C. Electro-galvanised nickel cadmium plated fastenings shall not be coated.

1.2.6 Coating Systems

A. Refer to surface preparation and painting schedules, Table 09900-1 to 09900-6.

1.3 Part 3 Execution

1.3.1 Examination

- A. The Contractor shall verify that surfaces are ready to receive coating treatment in accordance with instructions issued by the manufacturer and to this specification.
- B. Surfaces scheduled to be finished shall be examined prior to commencement of work. Conditions that may potentially affect proper application or spoilt applications shall be immediately reported.