| 4:12 | 12 | 3 | 4 | 5 | 6 | | | | |
|-------|----|---|----|----|----|--|--|--|--|
| | 16 | 3 | 5 | 7 | 8 | | | | |
| | 24 | 4 | 7 | 10 | 12 | | | | |
| | 32 | 6 | 9 | 13 | 16 | | | | |
| | 48 | 8 | 14 | 19 | 24 | | | | |
| 5:12 | 12 | 3 | 3 | 4 | 5 | | | | |
| | 16 | 3 | 4 | 5 | 7 | | | | |
| | 24 | 4 | 6 | 8 | 10 | | | | |
| | 32 | 5 | 8 | 10 | 13 | | | | |
| | 48 | 7 | 11 | 15 | 20 | | | | |
| 7:12 | 12 | 3 | 3 | 3 | 4 | | | | |
| | 16 | 3 | 3 | 4 | 5 | | | | |
| | 24 | 3 | 4 | 6 | 7 | | | | |
| | 32 | 4 | 6 | 8 | 10 | | | | |
| | 48 | 5 | 8 | 11 | 14 | | | | |
| 9:12 | 12 | 3 | 3 | 3 | 3 | | | | |
| | 16 | 3 | 3 | 3 | 4 | | | | |
| | 24 | 3 | 3 | 5 | 6 | | | | |
| | 32 | 3 | 4 | 6 | 8 | | | | |
| | 48 | 4 | 6 | 9 | 11 | | | | |
| 12:12 | 12 | 3 | 3 | 3 | 3 | | | | |
| | 16 | 3 | 3 | 3 | 3 | | | | |
| | 24 | 3 | 3 | 3 | 4 | | | | |
| | 32 | 3 | 3 | 4 | 5 | | | | |
| | 48 | 3 | 4 | 6 | 7 | | | | |

For SI: 1 inch = 25.4 mm, 1 foot = 304.8 mm, 1 pound per square foot = 47.8 N/m².

- a. 40d box (5" \times 0.162") or 16d sinker (3¹/₄" \times 0.148") nails are permitted to be substituted for 16d common (3¹/₂" \times 0.16") nails.
- b. Nailing requirements are permitted to be reduced 25 percent if nails are clinched.
- c. Rafter tie heel joint connections are not required where the ridge is supported by a load-bearing wall, header or ridge beam.
- d. When intermediate support of the rafter is provided by vertical struts or purlins to a load-bearing wall, the tabulated heel joint connection requirements are permitted to be reduced proportionally to the reduction in span.
- e. Equivalent nailing patterns are required for ceiling joist to ceiling joist lap splices.
- f. Connected members shall be of sufficient size to prevent splitting due to nailing.

2308.10.4.2 Notches and holes. Notching at the ends of rafters or ceiling joists shall not exceed one-fourth the depth. Notches in the top or bottom of the rafter or ceiling joist shall not exceed one-sixth the depth and shall not be located in the middle one-third of the span, except that a notch not exceeding one-third of the depth is permitted in the top of the rafter or ceiling joist not further from the face of the support than the depth of the member.