6 CO-ORDINATION AND MEETINGS (SECTION 01039)

6.1 Part 1 General

6.1.1 Related Sections

Section 01120 – Project Alteration Procedures.

Section 01700 - Contract Closeout.

6.1.2 Co-Ordination and Project Conditions

- A. The Contractor shall coordinate scheduling, submittals, and work of the various sections of the Contract Documents to ensure efficient and orderly sequence of the Works, with provisions for accommodating additional items later.
- B. The Contractor shall verify when appropriate, utility requirements and characteristics of operating equipment are compatible with irrigation utilities. Coordinate the work of various sections having interdependent responsibilities for installing, connecting to, and placing in service, such equipment.
- C. The Contractor shall coordinate space requirements, supports, and installation of mechanical and electrical Work. He shall utilise space efficiently to maximise accessibility for other installations, for maintenance and for repairs.
- D. The Contractor shall coordinate completion and clean-up of Work of separate sections in preparation for Contract Closeout.
- E. The Contractor shall coordinate access to site for correction of defective Work to minimise disruption to other parties' activities.

6.1.3 Site Handover Meeting

- A. The Engineer will schedule a meeting at the Project site prior to Contractor's occupancy and after signing the Agreement.
- B. Attendance Required: Representatives of DMAT, Engineer and Contractor.
- C. Agenda:
 - 1 Inspection of Site
 - 2 Observe and record conditions, obstructions, special features.
 - 3 Take photographs of salient features
 - 4 Identify and record location and elevation of benchmarks