Building Officials and Code Administrators International (BOCA). (1993). *The BOCA national plumbing code/1993*. BOCA Inc., Country Club Hills, Ill.

Burgett, L. B. (1973). "Fast check for ponding." Engineering Journal—American Institute of Steel Construction Inc., 10(1), 26–28.

Chinn, J. (1965). "Failure of simply supported flat roofs by ponding of rain." *Engineering Journal— American Institute of Steel Construction Inc.*, 3(2), 38–41.

Chinn, J., Mansouri, A. H., and Adams, S. F. (1969). "Ponding of liquids on flat roofs." *J. Struct. Div.*, 95(5), 797–808.

Factory Mutual Engineering Corp. (1991). *Loss prevention data 1–54, roof loads for new construction*, Factory Mutual Engineering Corp., Norwood, Mass.

Haussler, R. W. (1962). "Roof deflection caused by rainwater pools." *Civil Eng.*, 32, 58–59.

Heinzerling, J. E. (1971). "Structural design of steel joist roofs to resist ponding loads." Steel Joist Institute, Arlington, Va., Technical Digest No. 3.

Marino, F. J. (1966). "Ponding of two-way roof systems." *Engineering Journal—American Institute of Steel Construction Inc.*, 3(3), 93–100.

Salama, A. E., and Moody, M. L. (1967). "Analysis of beams and plates for ponding loads." *J. Struct. Div.*, 93(1), 109–126.

Sawyer, D. A. (1967). "Ponding of rainwater on flexible roof systems." *J. Struct. Div.*, 93(1), 127–148. Sawyer, D. A. (1969). "Roof-structural roof-drainage interactions." *J. Struct. Div.*, 94(1), 175–198. Southern Building Code Congress International (SBCCI). (1991). *Standard plumbing code*, SBCCI Inc., Birmingham, Ala.

Steel Joist Institute (SJI). (2007). Structural design of steel roofs to resist ponding loads, Technical Digest No. 3, Steel Joist Institute, Myrtle Beach, S.C.