FprEN 12464-1:2011 (E)

Table 5.16 — Industrial activities and crafts – Laundries and dry cleaning

Ref. no.	Type of area, task or activity	Ē _m	<i>UGR</i> ∟ –	<i>U</i> ₀	Ra –	Specific requirements
5.16.1	Goods in, marking and sorting	300	25	0,60	80	
5.16.2	Washing and dry cleaning	300	25	0,60	80	
5.16.3	Ironing, pressing	300	25	0,60	80	
5.16.4	Inspection and repairs	750	19	0,70	80	

Table 5.17 — Industrial activities and crafts – Leather and leather goods

Ref. no.	Type of area, task or activity	Ē _m	UGR _L	<i>U</i> ₀	R _a	Specific requirements
5.17.1	Work on vats, barrels, pits	200	25	0,40	40	
5.17.2	Fleshing, skiving, rubbing, tumbling of skins	300	25	0,40	80	
5.17.3	Saddlery work, shoe manufacture: stitching, sewing, polishing, shaping, cutting, punching	500	22	0,60	80	
5.17.4	Sorting	500	22	0,60	90	4 000 K ≤ T _{CP} ≤ 6 500 K
5.17.5	Leather dyeing (machine)	500	22	0,60	80	
5.17.6	Quality control	1 000	19	0,70	80	(#
5.17.7	Colour inspection	1 000	16	0,70	90	4 000 K ≤ T _{CP} ≤ 6 500 K
5.17.8	Shoe making	500	22	0,60	80	
5.17.9	Glove making	500	22	0,60	80	