



- All feasible engineering and work practice controls should be employed to limit the lead exposure levels at or below the permissible exposure limits.
- · Contractors should make sure that workers wear respirators designed to avoid inhaling lead.
- Contractors should not allow eating or drinking in the work area. Contractors should cover and seal all cabinets and food contact surfaces.
- Contractors should dispose off clothing worn in the room after working. Workers should not wear work clothing in other areas of the building. Work clothes should be laundered separately to eliminate further contamination.
- Awareness training shall be conducted for workers about dangers of exposure to lead systems
  and mandatory requirement of standards / methods to be followed to ensure safety and
  wellness of personal and public health.

## **COMPLIANCE DOCUMENTATION**

## Table 701.04(2): Documents Required

Project Stages	Submittal Documents
Design Permit Application	1. DM BLDG Al Sa'fat declaration.
Construction Completion Application	<ol> <li>Provide DCL certificate for lead containing materials that were used in the project.</li> <li>Delivery notes / purchase orders.</li> </ol>
After Completion	Not applicable.

## REFERENCES AND ADDITIONAL INFORMATION

Dubai Municipality. (2015). Standard DMS 20:2015—Specification for Paints and Varnishes.

Occupational Safety and Health Administration. (1996). OSHA's Technical Manual Section V, Chapter 3: Controlling Lead Exposures in the Construction Industry: Engineering and Work Practice Controls.