D. All individual circuits shall have their own residual current circuit breaker (RCCB's) in accordance with the regulations imposed by ADWEA and their associated group companies.

18.1.27 Portable Hand/Compressed Air Tools

- A. The Contractor shall ensure that:
 - Manufacturer's safe operating pressure for hoses and attachments should never be exceeded.
 - 2. All hoses exceeding 12mm inside diameter shall have a safety device at the source to reduce pressure in case of hose failure.
 - 3. Air supply lines to be protected from damage by vehicles and materials by use of channels or ramps.

18.1.28 Hazardous Substances

- A. Contractor shall submit to Engineer, details of the following:
 - 1. Hazardous substances should be identified from material hazard data sheets e.g. harmful, flammable.
 - 2. Provide a safe working procedure and provide the necessary information/training to relevant persons using the materials regarding:
 - a. Transport.
 - b. Handling and storage.
 - c. Exposure controls/personal protection.
 - d. Use.
 - e. Accidental release measures.
 - f. Fire fighting measures.
 - g. First aid.
 - h. Disposal considerations.
 - i. Ensure all containers holding hazardous substances have the correct hazard warning labels and identification clearly printed on them.