C. Contractor's Engineer Responsibilities: Sign surveyor's field notes or keep duplicate field notes.

## 8.1.9 Non-Compliance

- A. Work, which fails to meet the specified levels of accuracy, must not be rectified without approval.
- B. The Contractor shall propose rectification measures for parts of the Works, which do not meet the specified levels of accuracy to the Engineer for approval. Rectification measures necessitating removal and replacement of sub-standard work may not be approved. The Contractor shall pay all costs and losses associated with rectification of sub-standard work.

## 8.2 Part 2 Products

Not Used.

## 8.3 Part 3 Execution

Not Used.

**END OF SECTION**