Table 5.13 — Industrial activities and crafts – Foundries and metal casting

Ref. no.	Type of area, task or activity	Ēm	<i>UGR</i> _L	U_{0}	Ra	Specific requirements
		lx		-	_	
5.13.1	Man-size underfloor tunnels, cellars, etc.	50	-	0,40	20	Safety colours shall be recognisable.
5.13.2	Platforms	100	25	0,40	40	
5.13.3	Sand preparation	200	25	0,40	80	
5.13.4	Dressing room	200	25	0,40	80	
5.13.5	Work stations at cupola and mixer	200	25	0,40	80	
5.13.6	Casting bay	200	25	0,40	80	
5.13.7	Shake out areas	200	25	0,40	80	
5.13.8	Machine moulding	200	25	0,40	80	
5.13.9	Hand and core moulding	300	25	0,60	80	
5.13.10	Die casting	300	25	0,60	80	
5.13.11	Model building	500	22	0,60	80	

Table 5.14 — Industrial activities and crafts - Hairdressers

Ref. no.	Type of area, task or activity	Ē _m Ix	UGR _L	<i>U</i> ₀	R _a	Specific requirements
5.14.1	Hairdressing	500	19	0,60	90	

Table 5.15 — Industrial activities and crafts – Jewellery manufacturing

Ref. no.	Type of area, task or activity	Ē _m lx	UGR _L	<i>U</i> o –	R _a	Specific requirements
5.15.1	Working with precious stones	1 500	16	0,70	90	4 000 K ≤ T _{CP} ≤ 6 500 K
5.15.2	Manufacture of jewellery	1 000	16	0,70	90	
5.15.3	Watch making (manual)	1 500	16	0,70	80	
5.15.4	Watch making (automatic)	500	19	0,60	80	