

SHARMA AUTO WORKS - REPAIR ESTIMATE

Vehicle: Maruti Swift, MH-12-AB-1234

Front bumper replacement: INR 18,400

Headlamp assembly, left: INR 9,250

Paint and labour: INR 6,850

Total: INR 34,500