



Setting Up The Base:

1. Start with the P406 part with its largest surface face up.
2. Attach two P401 bars on either side of the P406 base.
3. Rivet four P403 corner gussets to the front and the back of the base.
4. At the top of the up bars, attach two P402 top sprocket gussets on either side.
 - a. Attach two P408 gussets on the inner sides of the up bars.
 - b. Attach four P410 top rollers, two for the front and back sides of both up bars.
5. At the bottom of the base, attach two P412 pivot gussets on either side.
6. Rivet the P411 motor plate at the bottom of P406.




Assembling First Stage:

1. Start with the P405 part with its largest surface face up.
2. Attach two P407 bars on either side of the P405 base.
3. Rivet two P409 bottom roller gussets to the front and the back of the base.
4. At the bottom of the up bars, attach four P408 gussets, two on either side of each bar.
5. At the top of the up bars, attach four P408 gussets, two on either side of each bar.
6. Attach four P410 top rollers, two for the front and back sides of both up bars.



Assembling Second Stage:

1. Start with the P414 3rd stage bar, with the side with rivet holes on both the top and the bottom facing you.
2. Attach two P415 gussets on the front and back sides of the third stage bar.
3. Attach two P408 gussets on either side of the bar, 1.5 inches from the bottom of stage.



Attaching Bearings to Elevator Stages:

1. Beginning from the elevator base up to the final stage, begin to attach bearings, screws and spacers.
 - a. For bearings that slide between the stages, use .5 in. dia. bearings.
 - b. Fill in the remaining space with respective 3D printed spacers.
 - c. For bearings that attach onto the sides of the elevator stages' bars, use .75 in. dia. Bearings.
 - d. Fill in the remaining space with respective 3D printed spacers.

Completing Elevator Assembly:

1. For the following steps, please seek and ask for additional assistance if necessary:
 - a. Elevator screws
 - b. Stage assembly
 - c. Elevator Bar
 - d. Spool
 - e. Chainspacers
 - f. Bearing shafts
 - g. Motor

