

R1 = 4x RTD resistance at 0°C (so 400 ohm for a 100 ohm RTD).
Use high quality 1% or better resistors

C3 = 100nF for 100 ohm RTD, 10nF for 1K

