



(a) Heading tracking under non-LoE actuator faults



(b) Pitch tracking error



(c) Commanded elevator (solid; FTC augmentation) vs physical (dashed)

