Handover Protocol

Draft from 3 photos · Created 10 Oct 2026

Protocol ID
HP-20261010-6989

Plate	Date	Mileage
—	10 Oct 2026	54,219 km

⚠ **4 damages detected**

4 moderate · Left side, Right side not yet checked

Damages

Evidence	Damage	Severity
	**rust** Front grille, central area · Photo: Front Corrosion and rust patches on the central section of the front grille, extending into the metal framework.	Moderate
	**rust** Front fender, lower left · Photo: Front Rust along the lower edge of the front fender, particularly near the wheel arch.	Moderate
	**rust** Rear fender, lower right · Photo: Rear Rust and corrosion along the lower edge of the rear fender, extending vertically.	Moderate
	**rust** Rear bumper, lower section · Photo: Rear Rust and degradation of the metal in the lower section of the rear bumper.	Moderate

ⓘ Not covered yet: left side, right side. Add photos to complete the protocol.

Photos



Front Damage 1, 2 marked

Left side Not captured



Rear Damage 3, 4 marked

Right side Not captured



Dashboard

Remarks

Handed over by · signature

Received by · signature