List of Bugs in BSIMSOI3.1 and Fixed in BSIMSOI3.1.1

Bug Reporters:
Yannick Mourier (Silvaco) yannick.mourier@silvaco.com
Shangli Wu (Cadence) shangliw@cadence.com
Josef Watts (IBM) jswatts@us.ibm.com
Richard Williams (IBM) rqw@us.ibm.com
Pin Su (UCB) pinsu@eecs.berkeley.edu

Description of Bug	Involved C-file	Bug Reporter	Fixed by
1. S/D swapping of the Igb conductances in AC	B3soiacld.c	Y. Mourier	Y. Mourier
2. The contribution of the Igc conductances in AC	B3soiacld.c	Y. Mourier	P. Su
3. Temperature derivative of the variable Vgst2Vtm	B3soild.c	S. Wu	S. Wu
4. Discontinuity in the length dependence of bipolar current	B3soild.c	J. Watts	J. Watts, R. Williams
5. Discontinuity in capMod=3	B3soild.c	J. Watts	J. Watts, P. Su
6. Making IgMod an alias for IgbMod to keep compatibility	B3soi.c	R. Williams	P. Su
7. Change the lower bound of pParam->B3SOIacde to 0.1	B3soicheck.c	R. Williams	P. Su