

Bellingham / Bellingham International / BLI




Communications

ATIS 134.45
 TWR 124.9
 GND 127.4
 CTAF 124.9
 UNICOM 122.95 For HIRL, MALSR
 PCL CTAF (Rwy 16; REIL Rwy 34 when
 twr is closed)

Navigation

Elevation 171' MSL
 TPA 1200' MSL fixed wing
 (1030' AGL); 700' MSL helo
 (530' AGL); 2000' MSL turbo
 (1830' AGL)
 Runway 16/34; 6701'x150'; ASPH-Grvd
 Lights Dusk-dawn, HIRL
 Latitude N 48° 47.56'
 Longitude W 122° 32.25'



Services

Fuel 100LL, Jet A

Fly Washington Passport Program

Stamp is Located at FBO, Bellingham Aviation
 Services. Green Mailbox on outside door, but stamp
 is inside FBO



Notes

Right-hand traffic on runway 16. Tower operations 0700-2230 local time. Noise abatement procedures in effect, VFR Rwy 16 Departures. Fly Rwy heading to pattern altitude beyond shoreline before turning.