


Lynden / Lynden Municipal Airport (Jansen Field) / 38W



Communications

Navigation

|                                     |                                         |
|-------------------------------------|-----------------------------------------|
| CTAF . . . . . 122.9                | Elevation . . . . . 106' MSL            |
| PCL . . . . . CTAF (For MIRL & BCN) | TPA. . . . . 1106' MSL (1000' AGL)      |
| AUTO UNICOM CTAF (3 CLICKS)         | Runway . . . . . 08/26; 2425'x40'; ASPH |
|                                     | Lights . . . . . NSTD, MIRL             |
|                                     | Latitude . . . . . N 48° 57.35'         |
|                                     | Longitude . . . . . W 122° 27.49'       |



Services

Fuel . . . . . 100LL  
(24-hour credit card fuel services)

**Fly Washington Passport Program**  
Stamp located in airport kiosk at east end of the airport.



Notes

Unattended. Night landings should be performed on runway 08, wind permitting.  
Displaced threshold Rwy 08 - 262' - 2163' avail. Displaced threshold Rwy 26 - 433' - 1992' available.  
Abbotsford (CYXX) ATIS: 119.8; Victoria Terminal (CYYJ) Approach: 132.7