

Renton / **Renton Municipal** / RNT




Communications

ATIS 126.95
 TWR 124.7
 GND 121.6
 CTAF 124.7
 UNICOM 122.85 and 122.95
 PCL CTAF (For MIRL Rwy 16/34; REIL Rwy 16/34 & twy lights)

Navigation

Elevation 32' MSL
 TPA 1032' MSL (1000' AGL)
 Runway 16/34; 5382'x200'; ASPH-CONC-Grvd
 Lights Dusk-dawn, NSTD, MIRL
 Latitude N 47° 29.59'
 Longitude W 122° 12.95'



Services

Fuel 100LL, Jet A, and Jet A+

Fly Washington Passport Program

Stamp located at the base of the tower, Airport Office.



Notes

Right-hand traffic on runway 34. Displaced threshold Rwy 16 - 300' - 5082' avail. Displaced threshold Rwy 34 - 340' - 5042' available. Seaplane base NW corner. Numerous flocks of birds. Noise abatement procedures contact arpt mgr. Be alert for Boeing production aircraft being towed across runway during hours when tower is closed. TPA west of fld is 1218' AGL due to terrain.