


OTHER TRAVERSE POINT TABLE				
POINT NUMBER	DESCRIPTION	NORTHING	EASTING	
900	RAILROAD SPIKE	712574.8448	1061225.5062	
929	FOUND SPIKE	710309.2852	1060029.1566	
931	BELL MONUMENT	710454.5962	1059699.0369	
938	2" BRASS DISK	713023.3629	1059680.1196	
942	BELL MONUMENT	713308.0868	1060518.9895	
953	1 1/2" DISK	714869.2991	1062846.4483	
1003	5/8" REBAR/CAP	711565.4353	1061109.2587	
1004	5/8" REBAR/CAP	711684.5964	1061078.0219	
1008	5/8" REBAR/CAP	712693.5603	1060876.7576	
1010	5/8" REBAR/CAP	712950.8628	1060500.0408	
1012	5/8" REBAR/CAP	711715.1404	1060319.5347	
1025	5/8" REBAR/CAP	713270.8637	1060409.9039	

COORDINATES ARE BASED ON STATE PLANE (GPS). ROTATED 0.1224 FROM PLAT.

ŀ	HUB AND M	DESCRIPTION	RAVERSE PO NORTHING T	EASTING
	901	HTS	712415.7571	1061269.2228
L	902	HTS	712059,4481	1061171.4273
-	903	HTS	711839.6417	1061132.2266
	904	HTS	711329.5981	1061022.3598
	905	HTS	711174.5568	1061006.1366
	906	HTS	711072,2084	1060869.0441
	907	HTS	711049.8771	1060697.4687
	908	HTS	710838.9697	1060770.6833
	909	HTS	710591.0590	1060777.1734
	910	HTS	710547.3842	1060634.5775
	911	HTS	710408,4817	1060697.2752
	912	HTS	713761.3514	1060002.1833
	913	HTS	713476.5333	1059817.9542
	914	HTS	713295.4980	1059763.9416
	917	HTS	710283.5503	1060607.3100
	918	HTS	710319.2806	1060490.4774
	919	HTS	710383.5039	1060435.6275
	920	HTS	710484.7065	1060106.5315
	921	HTS	710267.1147	1060180.4380
	922	HTS	711181.2673	1060271.7263
	923	HTS	711560.0820	1060142.4979
	924	HTS	712183.0223	1060238.9876
	925	HTS	712618.7786	1060157.6866
	926	HTS	712990.9665	1060159.7069
	930	HTS	710323.0899	1059833.2991
	932	HTS	710739.5082	1059722.5403
	934	HTS	711063.9289	1059810.8175
	935	HTS	711422.7225	1059935.9317
	936	HTS	711980.7125	1059812.2647
	937	HTS	712695.2271	1059729.1077
	939	HTS	713144.7118	1059720.1086
	941	HTS	713458.1509	1060519.6853
	944	HTS	712792.6659	1061568.1521
	945	HTS	713510.9494	1061949.4704
	946	HTS	713946,7068	1062147.4055
	947	HTS	710168.0553	1060391.5139
	948	HTS	710141.4658	1060544.8010
_	951	HTS	714332.7809	1062451.6425
	952	нтѕ	714733.9239	1062630.1618
	954	HTS	714917.6310	1062706.0220
	955	HTS	714854.8032	1062288.5856
_	956	HTS	714775.7489	1062262.7307
ĺ	957	HTS	714536.8243	1062111.8506
	958	HTS	714028.9900	1061813.1653
_	959	HTS	713462.2349	1061497.5293
	960	HTS	712970.9728	1061223.6058



LEGEND

---- EDGE OF GRAVEL ROAD LINE

HTS
HUB AND TACK SET (TRAVERSE POINT)

FOUND REBAR AND CAP OR IRON PIPE

SET REBAR AND CAP

FOUND MONUMENT

△ FOUND MAG NAIL AND FLASHER #28408

* FOUND SPIKE

No. Date By Appr.	HERRON ISLAND SURVEY CONTROL			
	OWNER/DEVELOPER: HMC MANAGEMENT, LLC. C/O CLAUDIA ELLSWORTH HERRON ISLAND MANAGER PO BOX 119 LAKEBAY, WASHINGTON 98349			
	ESA SELLINE ENGINEERING, INC. Land Development Professional Genericas (253)565-4491 • Seattle (206)824-1205 • FAX (253)565-8563 Land Planning & Use • Engineering • Surveying 1910-64th Avenue West, • Tacoma, WA 98466			
	DESIGNED DRAWN KRF CHECKED TCF DATE 10/12/11 SCALE 1"=100'			
	3 _{of} 3			
	ов но. 09-100			