Plant shutdown procedure
Step 1: Close inlet valve XV-101 and verify pressure is zero.
Step 2: Vent the line (café – test).