





Part Name (stl) - Comments	Image	Part location (in Red)
8mm plate bed bracket v2.03 - 3 per printer		
80mm fan mount v2.01 - 2 per printer		
y-axis belt clamp - 1 per printer		
y-axis belt clip v2.02 - 1 set per printer		Center of Y-Axis belt (under side)
Big_and_Small_Herring_Bone_Gear_Nucleus - 1 set per printer		
i3R_Compact_E3Dv6_Clamp_01 - 1 per printer		
i3R_Compact_E3Dv6_Extruder_3mm_01 - 1 per printer		
i3R_Compact_Guidler_3mm_01 - 1 per printer		



LCD spacer v2.01
- 4 per printer
(Between LCD and 8mm perspecs plate)





PSU corner
- 4 per printer





x-cable mgmnt v2.01
- 1 per printer





x-carriage 2mm spacer v2.05
- 1 per printer





x-carriage v2.05
- 1 per printer




x-endstop v2.03
- 1 per printer





x-idler mount v2.05
- 1 per printer





x-motor mount v2.05
- 1 per printer





y-axis bracket v2.03
- 4 per printer





y-endstop v2.01
- 1 per printer





y-idler v2.02
- 1 per printer





y-motor mount v2.02
- 2 per printer





z-endstop v2.03
- 1 per printer




z-motor mount left v2.01
- 1 per printer




z-motor mount right v2.01
- 1 per printer




z-top left v2.01
- 1 per printer




z-top right v2.01
- 1 per printer



Heat bearing mount 2.5mm
- 3 per printer



Ramps brackets
- 1 set per printer



25mm x M6 tube bush 2.01
- 2 per printer

