Valeo	PART NAME : Body_EB_EP_Sonafi	czerwca 02, 2021	15:35
	DRAWING REV: A	DRAWING No: V29120517_003	STATS COUNT : 3
	MEASUREMENT MADE BY : PAM_Jakubiec S.	COMMENT :	

```
#### SHEET 1/4
### Right view
## <AC-F3>
DIM LOC44= LOCATION OF CIRCLE D20_GG
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       20.000      0.100     -0.100     20.035      0.035      0.000 ------#--

## <AC-V4>
DIM CONCEN7= CONCENTRICITY FROM CIRCLE D20_GG TO LINE LIN_B
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.100      0.000      0.024      0.024      0.000 --#------

## <AC-F5>
DIM LOC45= POSITION OF PLANE PLN  _<AC-F5>
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z     -42.300                                     -42.304     -0.004
TP        RFS      0.200                 0.000      0.007      0.007      0.000 #--------


#### SHEET 2/4
### Section view A-A
## <A-C1>
DIM LOC1= LOCATION OF CYLINDER CYL_D44_GX_F
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       44.000      0.025      0.000     44.011      0.011      0.000 ---#-----

## <A-C5>
DIM LOC46= POSITION OF CYLINDER CYL_D44_GX_F  USE AXIS=AVERAGE  REF LENGTH=0.000
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z     -32.905                                     -32.906     -0.001
TP        MMC      0.200                 0.000      0.003      0.003      0.000 #--------

## <A-C6>
DIM LOC47= POSITION OF CYLINDER CYL_D44_GX_F  USE AXIS=AVERAGE  REF LENGTH=0.000
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X       0.000                                      -0.007     -0.007
TP        RFS      0.100                 0.000      0.014      0.014      0.000 -#-------

## <A-V11>
DIM CYLY1= CYLINDRICITY OF CYLINDER CYL_D44_GX_F
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.020      0.000      0.004      0.004      0.000 -#-------


### Front view
## <AD-C1> (x3)
DIM LOC2= LOCATION OF CIRCLE D6.15_1
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        6.150      0.050     -0.050      6.142     -0.008      0.000 ---#-----

DIM LOC3= LOCATION OF CIRCLE D6.15_Q
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        6.150      0.050     -0.050      6.137     -0.013      0.000 ---#-----

DIM LOC4= LOCATION OF CIRCLE D6.15_2
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        6.150      0.050     -0.050      6.133     -0.017      0.000 --#------
```

```
## <AD-C25>
DIM PERP1= PERPENDICULARITY OF LINE LIN_<AD-C25>,RFS TO PLANE PLN  _N,RFS EXTENDLENGTH=0.000
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M       0.000      0.500      0.000      0.017      0.017      0.000 #--------

## <AD-C2>
DIM LOC5= POSITION OF CIRCLE D6.15_Q
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X      34.000                                     34.005      0.005
TP       RFS      0.100                 0.000      0.011      0.011      0.000 #--------

## <AD-C6> (x3)
DIM DIST1= 2D DISTANCE FROM POINT PNT_6.15_1_1 TO POINT PNT_6.15_1_2 PAR TO POINT PNT_6.15_1_2,NO_RADIUS
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M       6.150      0.050     -0.050      6.122     -0.028      0.000 -#-------

DIM DIST2= 2D DISTANCE FROM POINT PNT_6.15_2_2 TO POINT PNT_6.15_2_1 PAR TO POINT PNT_6.15_2_1,NO_RADIUS
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M       6.150      0.050     -0.050      6.114     -0.036      0.000 -#-------

DIM DIST3= 2D DISTANCE FROM POINT PNT_6.15_3_1 TO POINT PNT_6.15_3_2 PAR TO POINT PNT_6.15_3_2,NO_RADIUS
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M       6.150      0.050     -0.050      6.130     -0.020      0.000 --#------

## <AD-C20>
DIM PERP2= PERPENDICULARITY OF LINE LIN_<AD-C20>,RFS TO PLANE PLN  _N,RFS EXTENDLENGTH=0.000
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M       0.000      0.500      0.000      0.019      0.019      0.000 #--------

## <AD-C21> (x3)
DIM LOC8= POSITION OF POINT PNT_6.15_MID_1
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X     -35.000                                    -34.993      0.007
Y       0.000                                     -0.013     -0.013
TP       RFS      0.200                 0.000      0.030      0.030      0.000 -#-------

DIM LOC6= POSITION OF POINT PNT_6.15_MID_2_AC
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X     -35.000                                    -34.993      0.007
Y       0.000                                     -0.006     -0.006
TP       RFS      0.200                 0.000      0.018      0.018      0.000 #--------

DIM LOC7= POSITION OF POINT PNT_6.15_MID_3
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X     -35.000                                    -34.993      0.007
Y       0.000                                      0.006      0.006
TP       RFS      0.200                 0.000      0.019      0.019      0.000 #--------

## <AD-F26> & <AD-F27> (x2)
DIM LOC9= POSITION OF CIRCLE D17.1_1
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X     -76.500                                    -76.573     -0.073
Y      14.100                                     14.091     -0.009
DF     17.100      0.200     -0.200                16.605     -0.495      0.295 <--------
TP       RFS      0.500                 0.000      0.147      0.147      0.000 --#------

DIM LOC10= POSITION OF CIRCLE D17.1_2
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X     -76.500                                    -76.566     -0.066
Y      14.100                                     14.076     -0.024
DF     17.100      0.200     -0.200                16.549     -0.551      0.351 <--------
TP       RFS      0.500                 0.000      0.141      0.141      0.000 --#------

## <AD-F14> (X4)
DIM LOC21= LOCATION OF POINT R8_AE_1_1
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
PR      8.000      1.000      0.000      8.714      0.715      0.000 ------#--
```

```
DIM LOC22= LOCATION OF POINT R8_AE_1_2
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
PR       8.000      1.000      0.000      8.533      0.533      0.000 ----#----

DIM LOC23= LOCATION OF POINT R8_AE_1_3
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
PR       8.000      1.000      0.000      8.181      0.182      0.000 -#-------

DIM LOC24= LOCATION OF POINT R8_AE_1_4
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
PR       8.000      1.000      0.000      8.625      0.625      0.000 -----#---

## <AD-F23> (x3)
DIM LOC25= LOCATION OF POINT R8_AE_2_1
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
PR       8.000      1.000      0.000      8.557      0.557      0.000 -----#---

DIM LOC26= LOCATION OF POINT R8_AE_2_2
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
PR       8.000      1.000      0.000      8.157      0.157      0.000 -#-------

DIM LOC27= LOCATION OF POINT R8_AE_2_3
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
PR       8.000      1.000      0.000      8.480      0.480      0.000 ----#----

## <AD-F18> (x3)
DIM LOC28= LOCATION OF POINT R8_AE_3_1
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
PR       8.000      1.000      0.000      8.659      0.659      0.000 -----#---

DIM LOC29= LOCATION OF POINT R8_AE_3_2
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
PR       8.000      1.000      0.000      8.104      0.103      0.000 #--------

DIM LOC30= LOCATION OF POINT R8_AE_3_3
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
PR       8.000      1.000      0.000      8.689      0.689      0.000 ------#--


### Section view AA-AA
## <AA-C1> (x3)
DIM DIST4= 2D DISTANCE FROM POINT PNT_8.15_3_1 TO POINT PNT_8.15_3_2 PAR TO POINT PNT_8.15_3_2,NO_RADIUS
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        8.150      0.200     -0.200      8.079     -0.071      0.000 --#------

DIM DIST5= 2D DISTANCE FROM POINT PNT_8.15_2_1 TO POINT PNT_8.15_2_2 PAR TO POINT PNT_8.15_2_2,NO_RADIUS
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        8.150      0.200     -0.200      8.094     -0.056      0.000 ---#-----

DIM DIST6= 2D DISTANCE FROM POINT PNT_8.15_1_1 TO POINT PNT_8.15_1_2 PAR TO POINT PNT_8.15_1_2,NO_RADIUS
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        8.150      0.200     -0.200      8.119     -0.031      0.000 ---#-----

## <AA-F2> (x3)
DIM LOC111= POSITION OF POINT PNT_8.15_MID_3
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X     -69.000                                     -69.013     -0.013
TP        RFS      0.200                 0.000      0.026      0.026      0.000 -#-------

DIM LOC112= POSITION OF POINT PNT_8.15_MID_2
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X     -69.000                                     -69.014     -0.014
TP        RFS      0.200                 0.000      0.027      0.027      0.000 -#-------

DIM LOC113= POSITION OF POINT PNT_8.15_MID_1
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X     -69.000                                     -69.015     -0.015
TP        RFS      0.200                 0.000      0.031      0.031      0.000 -#-------
```

```
### Left view
## <AE-F10> Total surface
DIM FLAT1= FLATNESS OF PLANE PLN  _N
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.350      0.000      0.059      0.059      0.000 -#-------

## <AE-F13> (x3)
DIM LOC17= POSITION OF PLANE PLN  _AE_1
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z     -10.000                                     -10.230     -0.230
TP        RFS      0.600                 0.000      0.461      0.461      0.000 ------#--

DIM LOC18= POSITION OF PLANE PLN  _AE_2
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z     -10.000                                     -10.251     -0.251
TP        RFS      0.600                 0.000      0.502      0.502      0.000 -------#-

DIM LOC19= POSITION OF PLANE PLN  _AE_3
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z     -10.000                                     -10.228     -0.228
TP        RFS      0.600                 0.000      0.455      0.455      0.000 ------#--

## <AE-F6> Total surface
DIM FLAT2= FLATNESS OF PLANE PLN  _N"
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.200      0.000      0.058      0.058      0.000 --#------

## <AE-C7>
DIM LOC20= POSITION OF PLANE PLN  _N"
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z     -16.000                                     -16.214     -0.214
TP        RFS      0.600                 0.000      0.428      0.428      0.000 ------#--


### Section view B-B
## <B-C4> & <B-C7>
## H1
DIM LOC11= POSITION OF CYLINDER CYL_D7.75_H1  USE AXIS=WORST (END PT)  REF LENGTH=0.000
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X     -32.600                                     -32.645     -0.045
Y      38.200                                      38.138     -0.062
DF      7.750      0.250     -0.250      0.280      7.780      0.030      0.000 -----#---
TP        MMC      0.500                 0.280      0.153      0.153      0.000 -#-------

## H2
DIM LOC12= POSITION OF CYLINDER CYL_D7.75_H2  USE AXIS=WORST (END PT)  REF LENGTH=0.000
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X       1.500                                       1.441     -0.059
Y     -14.300                                     -14.350     -0.050
DF      7.750      0.250     -0.250      0.278      7.778      0.028      0.000 ----#----
TP        MMC      0.500                 0.278      0.155      0.155      0.000 -#-------

## H3
DIM LOC13= POSITION OF CYLINDER CYL_D7.75_H3  USE AXIS=WORST (START PT)  REF LENGTH=0.000
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X     -64.000                                     -64.059     -0.059
Y     -23.600                                     -23.629     -0.029
DF      7.750      0.250     -0.250      0.292      7.792      0.042      0.000 -----#---
TP        MMC      0.500                 0.292      0.131      0.131      0.000 -#-------

### Section view N-N
## <N-C3> & <N-C6>
## H4
DIM LOC14= POSITION OF CYLINDER CYL_D7.75_H4  USE AXIS=WORST (START PT)  REF LENGTH=0.000
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X     -76.500                                     -76.560     -0.060
Y      14.100                                      14.067     -0.033
DF      7.750      0.250     -0.250      0.389      7.889      0.139      0.000 -------#-
TP        MMC      0.500                 0.389      0.137      0.137      0.000 -#-------
```

```
## H5
DIM LOC15= POSITION OF CYLINDER CYL_D7.75_H5  USE AXIS=WORST (START PT)  REF LENGTH=0.000
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X     -15.500                                     -15.597     -0.097
Y      30.900                                      30.859     -0.041
DF      7.750      0.250     -0.250      0.396      7.896      0.146      0.000 -------#-
TP        MMC      0.500                 0.396      0.211      0.211      0.000 --#------

## H6
DIM LOC16= POSITION OF CYLINDER CYL_D7.75_H6  USE AXIS=WORST (START PT)  REF LENGTH=0.000
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X     -40.000                                     -40.054     -0.054
Y     -45.700                                     -45.786     -0.086
DF      7.750      0.250     -0.250      0.383      7.883      0.133      0.000 ------#--
TP        MMC      0.500                 0.383      0.204      0.204      0.000 --#------


#### SHEET 3/4
### Section view D-D
## <D-F9> Between 2 clips (x6)
DIM FLAT4= FLATNESS OF PLANE PLN  _A1
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.200      0.000      0.030      0.030      0.000 -#-------

DIM FLAT5= FLATNESS OF PLANE PLN  _A2
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.200      0.000      0.022      0.022      0.000 #--------

DIM FLAT6= FLATNESS OF PLANE PLN  _A3
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.200      0.000      0.005      0.005      0.000 #--------

DIM FLAT7= FLATNESS OF PLANE PLN  _A4
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.200      0.000      0.053      0.053      0.000 --#------

DIM FLAT8= FLATNESS OF PLANE PLN  _A5
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.200      0.000      0.047      0.047      0.000 --#------

DIM FLAT9= FLATNESS OF PLANE PLN  _A6
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.200      0.000      0.017      0.017      0.000 #--------

## <D-F10> Total surface
DIM FLAT3= FLATNESS OF PLANE PLN  _A
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.350      0.000      0.134      0.134      0.000 ---#-----

## <D-V1> (x3)
DIM LOC31= LOCATION OF CIRCLE D12_1_GG
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       12.000     -0.009     -0.020     11.990     -0.010      0.000 --------#

DIM LOC32= LOCATION OF CIRCLE D12_2_GG
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       12.000     -0.009     -0.020     11.985     -0.015      0.000 ---#-----

DIM LOC33= LOCATION OF CIRCLE D12_3_GG
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       12.000     -0.009     -0.020     11.983     -0.017      0.000 --#------

## <D-F16> (x3)
DIM CONCEN1= CONCENTRICITY FROM CIRCLE D12_1_GG TO LINE LIN_B
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.050      0.000      0.002      0.002      0.000 #--------
```

```
DIM CONCEN2= CONCENTRICITY FROM CIRCLE D12_2_GG TO LINE LIN_B
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.050      0.000      0.000      0.000      0.000 #--------

DIM CONCEN3= CONCENTRICITY FROM CIRCLE D12_3_GG TO LINE LIN_B
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.050      0.000      0.002      0.002      0.000 #--------

## <D-V2> (x3)
DIM LOC34= LOCATION OF CIRCLE D10_1_GG
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       10.000      0.015      0.000     10.012      0.012      0.000 -------#-

DIM LOC35= LOCATION OF CIRCLE D10_2_GG
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       10.000      0.015      0.000     10.011      0.011      0.000 ------#--

DIM LOC36= LOCATION OF CIRCLE D10_3_GG
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       10.000      0.015      0.000     10.008      0.008      0.000 ----#----

## <D-F17> (x3)
DIM CONCEN4= CONCENTRICITY FROM CIRCLE D10_1_GG TO LINE LIN_B
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.050      0.000      0.009      0.009      0.000 -#-------

DIM CONCEN5= CONCENTRICITY FROM CIRCLE D10_2_GG TO LINE LIN_B
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.050      0.000      0.000      0.000      0.000 #--------

DIM CONCEN6= CONCENTRICITY FROM CIRCLE D10_3_GG TO LINE LIN_B
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.050      0.000      0.009      0.009      0.000 -#-------

## <D-F6>
DIM PERP3= PERPENDICULARITY OF LINE LIN_B,RFS TO PLANE PLN  _A,RFS EXTENDLENGTH=0.000
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.200      0.000      0.065      0.065      0.000 --#------

## <D-V7>
DIM STRA1= STRAIGHTNESS OF LINE LIN_B
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.050      0.000      0.009      0.009      0.000 -#-------

## <D-F11>
DIM LOC37= POSITION OF PLANE PLN  _H
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z     -22.985                                     -22.949      0.036
TP        RFS      0.400                 0.000      0.072      0.072      0.000 -#-------

## <D-F12>
DIM PERP4= PERPENDICULARITY OF PLANE PLN  _H,RFS TO LINE LIN_B,RFS
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.050      0.000      0.002      0.002      0.000 #--------

## <D-F13>
DIM LOC38= POSITION OF PLANE PLN  _G
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z     -73.560                                     -73.615     -0.055
TP        RFS      0.200                 0.000      0.110      0.110      0.000 ----#----
```

```
### Detail F
## <F-F7>  (x3)
DIM LOC39= LOCATION OF CIRCLE D8.09_1_GX
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       8.090      0.022      0.000      8.108      0.018      0.000 -------#-

DIM LOC40= LOCATION OF CIRCLE D8.09_2_GX
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       8.090      0.022      0.000      8.099      0.009      0.000 ---#-----

DIM LOC41= LOCATION OF CIRCLE D8.09_3_GX
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       8.090      0.022      0.000      8.098      0.008      0.000 ---#-----

## <F-F7> - cylinder
DIM LOC42= LOCATION OF CYLINDER CYL_D8.09_GX
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       8.090      0.022      0.000      8.098      0.008      0.000 ---#-----

## <F-F12>
DIM LOC43= POSITION OF CIRCLE D8.09_1_GX
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS              DEV     OUTTOL
X       0.000                                      0.001            0.001
Y       0.000                                     -0.001           -0.001
DF      8.090      0.022      0.000      0.018      8.108            0.018      0.000 -------#-
D1     12.000     -0.009     -0.020                11.986 CYLINDER CYL_D12_GG_B1 AT RFS
TP        MMC      0.020                 0.018      0.002            0.002      0.000 #--------

## <F-F11>
DIM LOC48= POSITION OF PLANE PLN  _P
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      12.675                                      12.614     -0.061
TP        RFS      0.300                 0.000      0.122      0.122      0.000 ---#-----


### Detail H
## <H-F1> (x3)
DIM LOC51= LOCATION OF CIRCLE D8.07_1_GX
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       8.070      0.022      0.000      8.075      0.005      0.000 --#------

DIM LOC52= LOCATION OF CIRCLE D8.07_2_GX
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       8.070      0.022      0.000      8.074      0.004      0.000 -#-------

DIM LOC53= LOCATION OF CIRCLE D8.07_3_GX
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       8.070      0.022      0.000      8.074      0.004      0.000 -#-------

## <H-F1> - cylinder
DIM LOC54= LOCATION OF CYLINDER CYL_D8.07_GX
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       8.070      0.022      0.000      8.074      0.004      0.000 -#-------

## <H-F15>
DIM LOC55= POSITION OF CYLINDER CYL_D8.07_GX  USE AXIS=AVERAGE  REF LENGTH=0.000
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS              DEV     OUTTOL
X       0.000                                     -0.001           -0.001
Y       0.000                                      0.000            0.000
DF      8.070      0.022      0.000      0.004      8.074            0.004      0.000 -#-------
D1     10.000      0.015      0.000                10.010 CYLINDER CYL_D10_GG_B2 AT RFS
TP        MMC      0.020                 0.004      0.002            0.002      0.000 #--------

## <H-V10> (x2)
DIM LOC56= LOCATION OF CIRCLE D13.5_1_GG
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D      13.500      0.018      0.000     13.511      0.011      0.000 -----#---
```

```
DIM LOC57= LOCATION OF CIRCLE D13.5_2_GG
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       13.500      0.018      0.000     13.512      0.012      0.000 ------#--

## <H-F16>
DIM CONCEN8= CONCENTRICITY FROM CIRCLE D13.5_1_GG TO LINE LIN_B
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.200      0.000      0.023      0.023      0.000 -#-------

## <H-F13>
DIM LOC49= POSITION OF PLANE PLN  _4.2
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      -4.200                                     -4.193      0.007
TP        RFS      0.200                 0.000      0.014      0.014      0.000 #--------

## <H-F17>
DIM LOC50= POSITION OF PLANE PLN  _14.1
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z     -14.100                                    -14.105     -0.005
TP        RFS      0.200                 0.000      0.010      0.010      0.000 #--------


### Detail G
## <G-V1> - circle (x3)
DIM LOC58= LOCATION OF CIRCLE D4_1
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        4.000     -0.016     -0.028      3.982     -0.018      0.000 -------#-

DIM LOC59= LOCATION OF CIRCLE D4_2
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        4.000     -0.016     -0.028      3.980     -0.020      0.000 -----#---

DIM LOC60= LOCATION OF CIRCLE D4_3
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        4.000     -0.016     -0.028      3.980     -0.020      0.000 ------#--

## <G-V1> - cylinder
DIM LOC61= LOCATION OF CYLINDER CYL_C
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        4.000     -0.016     -0.028      3.981     -0.019      0.000 ------#--

## <G-V6>
DIM LOC62= POSITION OF CYLINDER CYL_C  USE AXIS=AVERAGE  REF LENGTH=0.000
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X      33.580                                     33.587      0.007
TP        RFS      0.060                 0.000      0.014      0.014      0.000 --#------

## <G-V7>
DIM PERP5= PERPENDICULARITY OF CYLINDER CYL_C,RFS TO PLANE PLN  _K,RFS EXTENDLENGTH=0.000
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.200      0.000      0.005      0.005      0.000 #--------

## <G-F9>
DIM LOC63= POSITION OF PLANE PLN  _K
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z       1.510                                      1.513      0.003
TP        RFS      0.300                 0.000      0.006      0.006      0.000 #--------

## <G-F5>
DIM LOC64= LOCATION OF CIRCLE D4.1
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        4.100      0.050     -0.050      4.082     -0.018      0.000 --#------

## <G-F11>
DIM CONCEN9= CONCENTRICITY FROM CIRCLE D4.1 TO CYLINDER CYL_C
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.100      0.000      0.024      0.024      0.000 --#------
```

```
### Section view J-J
## <J-V19>
DIM LOC114= LOCATION OF CIRCLE D31.56_AB
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       31.560      0.200     -0.200     31.769      0.209      0.009 -------->

## <J-F20>
DIM CONCEN14= CONCENTRICITY FROM CIRCLE D31.56_AB TO CYLINDER CYL_D11.1_E
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.300      0.000      0.272      0.272      0.000 --------#

## <J-F23>
DIM LOC115= LOCATION OF CIRCLE D31.8
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       31.800      0.200     -0.200     31.933      0.133      0.000 -------#-

## <J-F24>
DIM CONCEN13= CONCENTRICITY FROM CIRCLE D31.8 TO CIRCLE D31.56_AB
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.200      0.000      0.123      0.123      0.000 -----#---

## <J-F10>
DIM LOC69= POSITION OF PLANE PLN  _L
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z       3.960                                      3.986      0.026
TP        RFS      0.300                 0.000      0.052      0.052      0.000 -#-------

## <J-V2>
DIM LOC65= LOCATION OF CYLINDER CYL_D11.1_E
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       11.100      0.028      0.010     11.113      0.013      0.000 -#-------

## <J-V13>
DIM LOC100= POSITION OF CYLINDER CYL_D11.1_E  USE AXIS=AVERAGE  REF LENGTH=0.000
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X      24.690                                     24.682     -0.008
TP        RFS      0.060                 0.000      0.015      0.015      0.000 --#------

## <J-F14>
DIM PERP6= PERPENDICULARITY OF CYLINDER CYL_D11.1_E,RFS TO PLANE PLN  _L,RFS EXTENDLENGTH=0.000
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.150      0.000      0.006      0.006      0.000 #--------

## <J-F11>
DIM LOC68= POSITION OF PLANE PLN  _AF
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z     -46.950                                    -47.006     -0.056
TP        RFS      0.300                 0.000      0.112      0.112      0.000 ---#-----

## <J-F21>
DIM LOC67= POSITION OF POINT PNT_8.2
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      -8.200                                     -8.286     -0.086
TP        RFS      0.300                 0.000      0.173      0.173      0.000 -----#---


### Section view L-L
## <L-F1> (x2)
## T1
DIM LOC70= LOCATION OF CYLINDER CYL_D3.7_L1
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        3.700      0.050     -0.050      3.727      0.027      0.000 ------#--

## T2
DIM LOC71= LOCATION OF CYLINDER CYL_D3.7_L2_Z
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        3.700      0.050     -0.050      3.717      0.017      0.000 -----#---
```

```
## <L-F6> (x2)
## T1
DIM LOC72= POSITION OF CYLINDER CYL_D3.7_L1  USE AXIS=AVERAGE  REF LENGTH=0.000
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
PR     21.500                                      21.488     -0.012
PA    287.000                                     286.987     -0.013
TP        RFS      0.200                 0.000      0.026      0.026      0.000 -#-------

## T2
DIM LOC73= POSITION OF CYLINDER CYL_D3.7_L2_Z  USE AXIS=AVERAGE  REF LENGTH=0.000
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
PR     21.500                                      21.514      0.014
PA     92.000                                      92.012      0.012
TP        RFS      0.200                 0.000      0.029      0.029      0.000 -#-------

## <L-F2> (x2)
## T1
DIM LOC74= LOCATION OF CIRCLE D4.7_L1
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        4.700      0.100     -0.100      4.721      0.021      0.000 -----#---

## T2
DIM LOC75= LOCATION OF CIRCLE D4.7_L2
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
Z       -1.000      0.100     -0.100     -1.000      0.000      0.000 ----#----
D        4.700      0.100     -0.100      4.719      0.019      0.000 -----#---

## <L-F7> (x2)
## T1
DIM CONCEN10= CONCENTRICITY FROM CIRCLE D4.7_L1 TO CYLINDER CYL_D3.7_L1
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.200      0.000      0.031      0.031      0.000 -#-------

## T2
DIM CONCEN11= CONCENTRICITY FROM CIRCLE D4.7_L2 TO CYLINDER CYL_D3.7_L2_Z
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.200      0.000      0.044      0.044      0.000 -#-------


### Detail K
## <K-F4> (x2)
DIM LOC76= POSITION OF POINT PNT_8.3_1
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y       8.030                                       8.124      0.094
TP        RFS      0.600                 0.000      0.189      0.189      0.000 --#------

DIM LOC77= POSITION OF POINT PNT_8.3_2
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y       8.030                                       8.101      0.071
TP        RFS      0.600                 0.000      0.142      0.142      0.000 --#------

## <K-F13> (x2)
DIM LOC78= POSITION OF POINT PNT_9.89_1
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y      -9.890                                      -9.792      0.098
TP        RFS      0.600                 0.000      0.195      0.195      0.000 --#------

DIM LOC79= POSITION OF POINT PNT_9.89_2
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y      -9.890                                      -9.827      0.063
TP        RFS      0.600                 0.000      0.126      0.126      0.000 -#-------


### Section view BC-BC
## <BE-F1>
DIM LOC80= LOCATION OF CYLINDER CYL_D3.98_D
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        3.980      0.050     -0.050      3.963     -0.017      0.000 --#------
```

```
## <BE-F2>
DIM LOC81= POSITION OF CYLINDER CYL_D3.98_D  USE AXIS=AVERAGE  REF LENGTH=0.000
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
PR     61.870                                       61.902      0.032
PA    159.000                                      159.038      0.038
TP        RFS      0.100                 0.000      0.105      0.105      0.005 -------->

## <BE-F3>
DIM PERP7= PERPENDICULARITY OF CYLINDER CYL_D3.98_D,RFS TO PLANE PLN  _A,RFS EXTENDLENGTH=0.000
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.350      0.000      0.004      0.004      0.000 #--------

## <BE-F6>
DIM LOC110= POSITION OF PLANE PLN  _0.7
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      -0.700                                      -0.754     -0.054
TP        RFS      0.400                 0.000      0.109      0.109      0.000 --#------


### Section view S-S
## <S-F5> (x2)
## (16.45)
DIM LOC82= POSITION OF POINT PNT_16.45_1
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      16.450                                      16.430     -0.020
TP        RFS      0.500                 0.000      0.040      0.040      0.000 #--------

DIM LOC83= POSITION OF POINT PNT_16.45_2
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      16.450                                      16.434     -0.016
TP        RFS      0.500                 0.000      0.031      0.031      0.000 #--------

## (18.255)
DIM LOC84= POSITION OF POINT PNT_18.255_1
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      18.225                                      18.190     -0.035
TP        RFS      0.500                 0.000      0.070      0.070      0.000 -#-------

DIM LOC85= POSITION OF POINT PNT_18.255_2
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      18.225                                      18.190     -0.035
TP        RFS      0.500                 0.000      0.070      0.070      0.000 -#-------

## <S-F6>
DIM LOC86= POSITION OF POINT PNT_15.81_1
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
PR     15.810                                      15.873      0.063
TP        RFS      0.600                 0.000      0.143      0.143      0.000 --#------

DIM LOC87= POSITION OF POINT PNT_15.81_2
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
PR     15.810                                      15.894      0.084
TP        RFS      0.600                 0.000      0.187      0.187      0.000 --#------

## <S-F7>
DIM LOC88= POSITION OF POINT PNT_18.08_1
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
PR     18.080                                      18.279      0.199
TP        RFS      0.600                 0.000      0.402      0.402      0.000 ------#--

DIM LOC89= POSITION OF POINT PNT_18.08_2
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
PR     18.080                                      18.278      0.198
TP        RFS      0.600                 0.000      0.400      0.400      0.000 ------#--
```

```
### Section view AJ-AJ
## <AJ-F1> (x2)
DIM LOC91= POSITION OF POINT PNT_28.445_2
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      28.445                                      28.389     -0.056
TP        RFS      0.500                 0.000      0.113      0.113      0.000 --#------

DIM LOC92= POSITION OF POINT PNT_28.445_2
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      28.445                                      28.386     -0.059
TP        RFS      0.500                 0.000      0.117      0.117      0.000 --#------

## <AJ-F4>
DIM LOC90= LOCATION OF CIRCLE D44.42
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       44.420      0.200     -0.200     44.516      0.096      0.000 ------#--

## <AJ-F5>
DIM CONCEN12= CONCENTRICITY FROM CIRCLE D44.42 TO LINE LIN_B
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.500      0.000      0.398      0.398      0.000 -------#-


### Section view R-R
## <R-F6> (x2)
DIM LOC93= POSITION OF POINT PNT_33.395_1
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      33.395                                      33.283     -0.112
TP        RFS      0.400                 0.000      0.224      0.224      0.000 -----#---

DIM LOC94= POSITION OF POINT PNT_33.395_2
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      33.395                                      33.272     -0.123
TP        RFS      0.400                 0.000      0.245      0.245      0.000 -----#---

## <R-F5>
DIM LOC95= POSITION OF POINT PNT_34.545
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      34.545                                      34.445     -0.100
TP        RFS      0.400                 0.000      0.201      0.201      0.000 ----#----

## <R-F4>
DIM LOC96= POSITION OF PLANE PLN  _M
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      12.700                                      12.593     -0.107
TP        RFS      0.400                 0.000      0.215      0.215      0.000 ----#----


### Detail Q
## <Q-F6> (x2)
DIM PROF1= PROFILE OF SURFACE OF SET SCN_<Q-F6>_1    FORMANDLOCATION
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.400      0.000      0.145      0.145      0.000 ---#-----

DIM PROF2= PROFILE OF SURFACE OF SET SCN_<Q-F6>_2    FORMANDLOCATION
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.400      0.000      0.114      0.114      0.000 --#------

## <Q-F14>
DIM PROF3= PROFILE OF SURFACE OF SET SCN_<Q-F14>    FORMANDLOCATION
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.400      0.000      0.465      0.465      0.065 -------->

## <Q-V9> (x3)
DIM LOC97= POSITION OF POINT PNT<Q-F9>_1
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y        0.000                                      -0.071     -0.071
TP        RFS      0.500                 0.000      0.142      0.142      0.000 --#------
```

```
DIM LOC98= POSITION OF POINT PNT<Q-F9>_2_R
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y       0.000                                       -0.071     -0.071
TP        RFS      0.500                 0.000       0.142      0.142      0.000 --#------

DIM LOC99= POSITION OF POINT PNT<Q-F9>_3
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y       0.000                                       -0.076     -0.076
TP        RFS      0.500                 0.000       0.151      0.151      0.000 --#------

## <Q-V12> (x3)  Linia_R
DIM LOC66= POSITION OF POINT PNT<Q-V12>_1
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y      -1.000                                       -1.009     -0.009
TP        RFS      0.250                 0.000       0.018      0.018      0.000 #--------

DIM LOC126= POSITION OF POINT PNT<Q-V12>_2
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y      -1.000                                       -1.007     -0.007
TP        RFS      0.250                 0.000       0.014      0.014      0.000 #--------

DIM LOC127= POSITION OF POINT PNT<Q-V12>_3
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y      -1.000                                       -1.004     -0.004
TP        RFS      0.250                 0.000       0.008      0.008      0.000 #--------

## <Q-V12> (x3)  Punkt_R
DIM LOC119= POSITION OF POINT PNT<Q-V12>_1
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y      -1.000                                       -1.144     -0.144
TP        RFS      0.250                 0.000       0.288      0.288      0.038 -------->

DIM LOC124= POSITION OF POINT PNT<Q-V12>_2
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y      -1.000                                       -1.137     -0.137
TP        RFS      0.250                 0.000       0.274      0.274      0.024 -------->

DIM LOC125= POSITION OF POINT PNT<Q-V12>_3
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y      -1.000                                       -1.129     -0.129
TP        RFS      0.250                 0.000       0.258      0.258      0.008 -------->

## <Q-F3> (x4)
DIM LOC103= POSITION OF POINT PNT<Q-F3>_1
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y      -0.900                                       -1.098     -0.198
TP        RFS      0.500                 0.000       0.395      0.395      0.000 -------#-

DIM LOC104= POSITION OF POINT PNT<Q-F3>_2
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y      -0.900                                       -1.091     -0.191
TP        RFS      0.500                 0.000       0.383      0.383      0.000 ------#--

DIM LOC105= POSITION OF POINT PNT<Q-F3>_3
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y      -0.900                                       -1.088     -0.188
TP        RFS      0.500                 0.000       0.375      0.375      0.000 ------#--

DIM LOC106= POSITION OF POINT PNT<Q-F3>_4
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y      -0.900                                       -1.076     -0.176
TP        RFS      0.500                 0.000       0.351      0.351      0.000 ------#--
```

```
## <Q-V8> (x3)
DIM LOC107= POSITION OF POINT PNT<Q-V8>_1
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y       0.000                                       0.048      0.048
TP        RFS      0.500                 0.000      0.096      0.096      0.000 -#-------

DIM LOC108= POSITION OF POINT PNT<Q-V8>_2
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y       0.000                                       0.053      0.053
TP        RFS      0.500                 0.000      0.105      0.105      0.000 -#-------

DIM LOC109= POSITION OF POINT PNT<Q-V8>_3
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y       0.000                                       0.042      0.042
TP        RFS      0.500                 0.000      0.084      0.084      0.000 -#-------
```