Valeo	PART NAME : Body_EB_EP_Sonafi	maja 13, 2021	21:30
	DRAWING REV: A	DRAWING No: V29120517_003	STATS COUNT : 1
	MEASUREMENT MADE BY : REX_GAZDA	COMMENT :	

```
#### SHEET 1/4
### Right view
## <AC-F3>
DIM LOC44= LOCATION OF CIRCLE D20_GG
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       20.000      0.100     -0.100     20.034      0.034      0.000 ------#--

## <AC-V4>
DIM CONCEN7= CONCENTRICITY FROM CIRCLE D20_GG TO LINE LIN_B
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.100      0.000      0.023      0.023      0.000 --#------

## <AC-F5>
DIM LOC45= POSITION OF PLANE PLN  _<AC-F5>
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z     -42.300                                     -42.299      0.001
TP        RFS      0.200                 0.000      0.002      0.002      0.000 #--------


#### SHEET 2/4
### Section view A-A
## <A-C1>
DIM LOC1= LOCATION OF CYLINDER CYL_D44_GX_F
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       44.000      0.025      0.000     44.011      0.011      0.000 ---#-----

## <A-C5>
DIM LOC46= POSITION OF CYLINDER CYL_D44_GX_F  USE AXIS=AVERAGE  REF LENGTH=0.000
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z     -32.905                                     -32.908     -0.003
TP        MMC      0.200                 0.000      0.006      0.006      0.000 #--------

## <A-C6>
DIM LOC47= POSITION OF CYLINDER CYL_D44_GX_F  USE AXIS=AVERAGE  REF LENGTH=0.000
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X       0.000                                       0.003      0.003
TP        RFS      0.100                 0.000      0.006      0.006      0.000 #--------

## <A-V11>
DIM CYLY1= CYLINDRICITY OF CYLINDER CYL_D44_GX_F
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.020      0.000      0.006      0.006      0.000 --#------


### Front view
## <AD-C1> (x3)
DIM LOC2= LOCATION OF CIRCLE D6.15_1
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        6.150      0.050     -0.050      6.142     -0.008      0.000 ---#-----

DIM LOC3= LOCATION OF CIRCLE D6.15_Q
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        6.150      0.050     -0.050      6.139     -0.011      0.000 ---#-----

DIM LOC4= LOCATION OF CIRCLE D6.15_2
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        6.150      0.050     -0.050      6.138     -0.012      0.000 ---#-----
```

```
## <AD-C25>
DIM PERP1= PERPENDICULARITY OF LINE LIN_<AD-C25>,RFS TO PLANE PLN  _N,RFS EXTENDLENGTH=0.000
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M       0.000      0.500      0.000      0.039      0.039      0.000 #--------

## <AD-C2>
DIM LOC5= POSITION OF CIRCLE D6.15_Q
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X      34.000                                     34.009      0.009
TP       RFS      0.100                 0.000      0.018      0.018      0.000 -#-------

## <AD-C6> (x3)
DIM DIST1= 2D DISTANCE FROM POINT PNT_6.15_1_1 TO POINT PNT_6.15_1_2 PAR TO POINT PNT_6.15_1_2,NO_RADIUS
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M       6.150      0.050     -0.050      6.123     -0.027      0.000 --#------

DIM DIST2= 2D DISTANCE FROM POINT PNT_6.15_2_2 TO POINT PNT_6.15_2_1 PAR TO POINT PNT_6.15_2_1,NO_RADIUS
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M       6.150      0.050     -0.050      6.121     -0.029      0.000 -#-------

DIM DIST3= 2D DISTANCE FROM POINT PNT_6.15_3_1 TO POINT PNT_6.15_3_2 PAR TO POINT PNT_6.15_3_2,NO_RADIUS
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M       6.150      0.050     -0.050      6.131     -0.019      0.000 --#------

## <AD-C20>
DIM PERP2= PERPENDICULARITY OF LINE LIN_<AD-C20>,RFS TO PLANE PLN  _N,RFS EXTENDLENGTH=0.000
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M       0.000      0.500      0.000      0.033      0.033      0.000 #--------

## <AD-C21> (x3)
DIM LOC8= POSITION OF POINT PNT_6.15_MID_1
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X     -35.000                                    -34.992      0.008
Y       0.000                                      0.034      0.034
TP       RFS      0.200                 0.000      0.070      0.070      0.000 ---#-----

DIM LOC6= POSITION OF POINT PNT_6.15_MID_2_AC
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X     -35.000                                    -34.990      0.010
Y       0.000                                      0.014      0.014
TP       RFS      0.200                 0.000      0.034      0.034      0.000 -#-------

DIM LOC7= POSITION OF POINT PNT_6.15_MID_3
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X     -35.000                                    -34.990      0.010
Y       0.000                                      0.002      0.002
TP       RFS      0.200                 0.000      0.021      0.021      0.000 #--------

## <AD-F26> & <AD-F27> (x2)
DIM LOC9= POSITION OF CIRCLE D17.1_1
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X     -76.500                                    -76.487      0.013
Y      14.100                                     14.069     -0.031
DF     17.100      0.200     -0.200                16.561     -0.539      0.339 <--------
TP       RFS      0.500                 0.000      0.067      0.067      0.000 -#-------

DIM LOC10= POSITION OF CIRCLE D17.1_2
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X     -76.500                                    -76.500      0.000
Y      14.100                                     14.017     -0.083
DF     17.100      0.200     -0.200                16.589     -0.511      0.311 <--------
TP       RFS      0.500                 0.000      0.166      0.166      0.000 --#------

## <AD-F14> (X4)
DIM LOC21= LOCATION OF POINT R8_AE_1_1
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
PR      8.000      1.000      0.000      8.642      0.643      0.000 -----#---
```

```
DIM LOC22= LOCATION OF POINT R8_AE_1_2
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
PR       8.000      1.000      0.000      8.505      0.505      0.000 ----#----

DIM LOC23= LOCATION OF POINT R8_AE_1_3
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
PR       8.000      1.000      0.000      8.175      0.175      0.000 -#-------

DIM LOC24= LOCATION OF POINT R8_AE_1_4
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
PR       8.000      1.000      0.000      8.579      0.579      0.000 -----#---

## <AD-F23> (x3)
DIM LOC25= LOCATION OF POINT R8_AE_2_1
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
PR       8.000      1.000      0.000      8.584      0.584      0.000 -----#---

DIM LOC26= LOCATION OF POINT R8_AE_2_2
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
PR       8.000      1.000      0.000      8.174      0.173      0.000 -#-------

DIM LOC27= LOCATION OF POINT R8_AE_2_3
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
PR       8.000      1.000      0.000      8.494      0.493      0.000 ----#----

## <AD-F18> (x3)
DIM LOC28= LOCATION OF POINT R8_AE_3_1
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
PR       8.000      1.000      0.000      8.611      0.611      0.000 -----#---

DIM LOC29= LOCATION OF POINT R8_AE_3_2
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
PR       8.000      1.000      0.000      8.045      0.045      0.000 #--------

DIM LOC30= LOCATION OF POINT R8_AE_3_3
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
PR       8.000      1.000      0.000      8.640      0.640      0.000 -----#---


### Section view AA-AA
## <AA-C1> (x3)
DIM DIST4= 2D DISTANCE FROM POINT PNT_8.15_3_1 TO POINT PNT_8.15_3_2 PAR TO POINT PNT_8.15_3_2,NO_RADIUS
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        8.150      0.200     -0.200      8.085     -0.065      0.000 ---#-----

DIM DIST5= 2D DISTANCE FROM POINT PNT_8.15_2_1 TO POINT PNT_8.15_2_2 PAR TO POINT PNT_8.15_2_2,NO_RADIUS
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        8.150      0.200     -0.200      8.109     -0.041      0.000 ---#-----

DIM DIST6= 2D DISTANCE FROM POINT PNT_8.15_1_1 TO POINT PNT_8.15_1_2 PAR TO POINT PNT_8.15_1_2,NO_RADIUS
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        8.150      0.200     -0.200      8.123     -0.027      0.000 ---#-----

## <AA-F2> (x3)
DIM LOC111= POSITION OF POINT PNT_8.15_MID_3
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X     -69.000                                     -68.995      0.005
TP        RFS      0.200                 0.000      0.011      0.011      0.000 #--------

DIM LOC112= POSITION OF POINT PNT_8.15_MID_2
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X     -69.000                                     -69.007     -0.007
TP        RFS      0.200                 0.000      0.014      0.014      0.000 #--------

DIM LOC113= POSITION OF POINT PNT_8.15_MID_1
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X     -69.000                                     -69.018     -0.018
TP        RFS      0.200                 0.000      0.037      0.037      0.000 -#-------
```

```
### Left view
## <AE-F10> Total surface
DIM FLAT1= FLATNESS OF PLANE PLN  _N
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.350      0.000      0.105      0.105      0.000 --#------

## <AE-F13> (x3)
DIM LOC17= POSITION OF PLANE PLN  _AE_1
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z     -10.000                                      -9.983      0.017
TP        RFS      0.600                 0.000      0.034      0.034      0.000 #--------

DIM LOC18= POSITION OF PLANE PLN  _AE_2
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z     -10.000                                     -10.134     -0.134
TP        RFS      0.600                 0.000      0.269      0.269      0.000 ----#----

DIM LOC19= POSITION OF PLANE PLN  _AE_3
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z     -10.000                                     -10.022     -0.022
TP        RFS      0.600                 0.000      0.044      0.044      0.000 #--------

## <AE-F6> Total surface
DIM FLAT2= FLATNESS OF PLANE PLN  _N"
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.200      0.000      0.068      0.068      0.000 ---#-----

## <AE-C7>
DIM LOC20= POSITION OF PLANE PLN  _N"
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z     -16.000                                     -16.034     -0.034
TP        RFS      0.600                 0.000      0.068      0.068      0.000 -#-------


### Section view B-B
## <B-C4> & <B-C7>
## H1
DIM LOC11= POSITION OF CYLINDER CYL_D7.75_H1  USE AXIS=WORST (END PT)  REF LENGTH=0.000
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X     -32.600                                     -32.609     -0.009
Y      38.200                                      38.122     -0.078
DF      7.750      0.250     -0.250      0.270      7.770      0.020      0.000 ----#----
TP        MMC      0.500                 0.270      0.157      0.157      0.000 -#-------

## H2
DIM LOC12= POSITION OF CYLINDER CYL_D7.75_H2  USE AXIS=WORST (END PT)  REF LENGTH=0.000
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X       1.500                                       1.420     -0.080
Y     -14.300                                     -14.377     -0.077
DF      7.750      0.250     -0.250      0.259      7.759      0.009      0.000 ----#----
TP        MMC      0.500                 0.259      0.223      0.223      0.000 --#------

## H3
DIM LOC13= POSITION OF CYLINDER CYL_D7.75_H3  USE AXIS=WORST (END PT)  REF LENGTH=0.000
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X     -64.000                                     -63.997      0.003
Y     -23.600                                     -23.669     -0.069
DF      7.750      0.250     -0.250      0.286      7.786      0.036      0.000 -----#---
TP        MMC      0.500                 0.286      0.138      0.138      0.000 -#-------

### Section view N-N
## <N-C3> & <N-C6>
## H4
DIM LOC14= POSITION OF CYLINDER CYL_D7.75_H4  USE AXIS=WORST (END PT)  REF LENGTH=0.000
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X     -76.500                                     -76.498      0.002
Y      14.100                                      14.030     -0.070
DF      7.750      0.250     -0.250      0.389      7.889      0.139      0.000 ------#--
TP        MMC      0.500                 0.389      0.140      0.140      0.000 -#-------
```

```
## H5
DIM LOC15= POSITION OF CYLINDER CYL_D7.75_H5  USE AXIS=WORST (END PT)  REF LENGTH=0.000
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X     -15.500                                     -15.501     -0.001
Y      30.900                                      30.811     -0.089
DF      7.750      0.250     -0.250      0.418      7.918      0.168      0.000 -------#-
TP        MMC      0.500                 0.418      0.178      0.178      0.000 -#-------

## H6
DIM LOC16= POSITION OF CYLINDER CYL_D7.75_H6  USE AXIS=WORST (END PT)  REF LENGTH=0.000
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X     -40.000                                     -39.990      0.010
Y     -45.700                                     -45.861     -0.161
DF      7.750      0.250     -0.250      0.397      7.897      0.147      0.000 -------#-
TP        MMC      0.500                 0.397      0.322      0.322      0.000 ---#-----


#### SHEET 3/4
### Section view D-D
## <D-F9> Between 2 clips (x6)
DIM FLAT4= FLATNESS OF PLANE PLN  _A1
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.200      0.000      0.079      0.079      0.000 ---#-----

DIM FLAT5= FLATNESS OF PLANE PLN  _A2
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.200      0.000      0.033      0.033      0.000 -#-------

DIM FLAT6= FLATNESS OF PLANE PLN  _A3
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.200      0.000      0.014      0.014      0.000 #--------

DIM FLAT7= FLATNESS OF PLANE PLN  _A4
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.200      0.000      0.034      0.034      0.000 -#-------

DIM FLAT8= FLATNESS OF PLANE PLN  _A5
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.200      0.000      0.026      0.026      0.000 -#-------

DIM FLAT9= FLATNESS OF PLANE PLN  _A6
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.200      0.000      0.023      0.023      0.000 -#-------

## <D-F10> Total surface
DIM FLAT3= FLATNESS OF PLANE PLN  _A
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.350      0.000      0.109      0.109      0.000 --#------

## <D-V1> (x3)
DIM LOC31= LOCATION OF CIRCLE D12_1_GG
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       12.000     -0.009     -0.020     11.990     -0.010      0.000 --------#

DIM LOC32= LOCATION OF CIRCLE D12_2_GG
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       12.000     -0.009     -0.020     11.987     -0.013      0.000 -----#---

DIM LOC33= LOCATION OF CIRCLE D12_3_GG
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       12.000     -0.009     -0.020     11.985     -0.015      0.000 ----#----

## <D-F16> (x3)
DIM CONCEN1= CONCENTRICITY FROM CIRCLE D12_1_GG TO LINE LIN_B
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.050      0.000      0.006      0.006      0.000 -#-------
```

```
DIM CONCEN2= CONCENTRICITY FROM CIRCLE D12_2_GG TO LINE LIN_B
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.050      0.000      0.000      0.000      0.000 #--------

DIM CONCEN3= CONCENTRICITY FROM CIRCLE D12_3_GG TO LINE LIN_B
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.050      0.000      0.006      0.006      0.000 -#-------

## <D-V2> (x3)
DIM LOC34= LOCATION OF CIRCLE D10_1_GG
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       10.000      0.015      0.000     10.013      0.013      0.000 -------#-

DIM LOC35= LOCATION OF CIRCLE D10_2_GG
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       10.000      0.015      0.000     10.012      0.012      0.000 ------#--

DIM LOC36= LOCATION OF CIRCLE D10_3_GG
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       10.000      0.015      0.000     10.008      0.008      0.000 ----#----

## <D-F17> (x3)
DIM CONCEN4= CONCENTRICITY FROM CIRCLE D10_1_GG TO LINE LIN_B
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.050      0.000      0.006      0.006      0.000 -#-------

DIM CONCEN5= CONCENTRICITY FROM CIRCLE D10_2_GG TO LINE LIN_B
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.050      0.000      0.000      0.000      0.000 #--------

DIM CONCEN6= CONCENTRICITY FROM CIRCLE D10_3_GG TO LINE LIN_B
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.050      0.000      0.006      0.006      0.000 -#-------

## <D-F6>
DIM PERP3= PERPENDICULARITY OF LINE LIN_B,RFS TO PLANE PLN  _A,RFS EXTENDLENGTH=0.000
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.200      0.000      0.116      0.116      0.000 -----#---

## <D-V7>
DIM STRA1= STRAIGHTNESS OF LINE LIN_B
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.050      0.000      0.006      0.006      0.000 -#-------

## <D-F11>
DIM LOC37= POSITION OF PLANE PLN  _H
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z     -22.985                                     -23.017     -0.032
TP        RFS      0.400                 0.000      0.064      0.064      0.000 -#-------

## <D-F12>
DIM PERP4= PERPENDICULARITY OF PLANE PLN  _H,RFS TO LINE LIN_B,RFS
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.050      0.000      0.006      0.006      0.000 -#-------

## <D-F13>
DIM LOC38= POSITION OF PLANE PLN  _G
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z     -73.560                                     -73.532      0.028
TP        RFS      0.200                 0.000      0.056      0.056      0.000 --#------
```

```
### Detail F
## <F-F7>  (x3)
DIM LOC39= LOCATION OF CIRCLE D8.09_1_GX
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        8.090      0.022      0.000      8.110      0.020      0.000 --------#

DIM LOC40= LOCATION OF CIRCLE D8.09_2_GX
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        8.090      0.022      0.000      8.099      0.009      0.000 ---#-----

DIM LOC41= LOCATION OF CIRCLE D8.09_3_GX
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        8.090      0.022      0.000      8.097      0.007      0.000 ---#-----

## <F-F7> - cylinder
DIM LOC42= LOCATION OF CYLINDER CYL_D8.09_GX
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        8.090      0.022      0.000      8.097      0.007      0.000 --#------

## <F-F12>
DIM LOC43= POSITION OF CIRCLE D8.09_1_GX
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS              DEV     OUTTOL
X       0.000                                     -0.001           -0.001
Y       0.000                                      0.001            0.001
DF      8.090      0.022      0.000      0.020      8.110            0.020      0.000 --------#
D1     12.000     -0.009     -0.020                11.987 CYLINDER CYL_D12_GG_B1 AT RFS
TP        MMC      0.020                 0.020      0.003            0.003      0.000 #--------

## <F-F11>
DIM LOC48= POSITION OF PLANE PLN  _P
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      12.675                                      12.669     -0.006
TP        RFS      0.300                 0.000      0.012      0.012      0.000 #--------


### Detail H
## <H-F1> (x3)
DIM LOC51= LOCATION OF CIRCLE D8.07_1_GX
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        8.070      0.022      0.000      8.075      0.005      0.000 -#-------

DIM LOC52= LOCATION OF CIRCLE D8.07_2_GX
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        8.070      0.022      0.000      8.074      0.004      0.000 -#-------

DIM LOC53= LOCATION OF CIRCLE D8.07_3_GX
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        8.070      0.022      0.000      8.074      0.004      0.000 -#-------

## <H-F1> - cylinder
DIM LOC54= LOCATION OF CYLINDER CYL_D8.07_GX
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        8.070      0.022      0.000      8.074      0.004      0.000 -#-------

## <H-F15>
DIM LOC55= POSITION OF CYLINDER CYL_D8.07_GX  USE AXIS=AVERAGE  REF LENGTH=0.000
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS              DEV     OUTTOL
X       0.000                                      0.000            0.000
Y       0.000                                      0.003            0.003
DF      8.070      0.022      0.000      0.004      8.074            0.004      0.000 -#-------
D1     10.000      0.015      0.000                10.011 CYLINDER CYL_D10_GG_B2 AT RFS
TP        MMC      0.020                 0.004      0.005            0.005      0.000 -#-------

## <H-V10> (x2)
DIM LOC56= LOCATION OF CIRCLE D13.5_1_GG
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       13.500      0.018      0.000     13.513      0.013      0.000 ------#--
```

```
DIM LOC57= LOCATION OF CIRCLE D13.5_2_GG
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       13.500      0.018      0.000     13.514      0.014      0.000 -------#-

## <H-F16>
DIM CONCEN8= CONCENTRICITY FROM CIRCLE D13.5_1_GG TO LINE LIN_B
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.200      0.000      0.018      0.018      0.000 #--------

## <H-F13>
DIM LOC49= POSITION OF PLANE PLN  _4.2
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      -4.200                                     -4.198      0.002
TP        RFS      0.200                 0.000      0.003      0.003      0.000 #--------

## <H-F17>
DIM LOC50= POSITION OF PLANE PLN  _14.1
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z     -14.100                                    -14.109     -0.009
TP        RFS      0.200                 0.000      0.018      0.018      0.000 #--------


### Detail G
## <G-V1> - circle (x3)
DIM LOC58= LOCATION OF CIRCLE D4_1
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        4.000     -0.016     -0.028      3.982     -0.018      0.000 -------#-

DIM LOC59= LOCATION OF CIRCLE D4_2
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        4.000     -0.016     -0.028      3.981     -0.019      0.000 -------#-

DIM LOC60= LOCATION OF CIRCLE D4_3
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        4.000     -0.016     -0.028      3.982     -0.018      0.000 -------#-

## <G-V1> - cylinder
DIM LOC61= LOCATION OF CYLINDER CYL_C
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        4.000     -0.016     -0.028      3.982     -0.018      0.000 -------#-

## <G-V6>
DIM LOC62= POSITION OF CYLINDER CYL_C  USE AXIS=AVERAGE  REF LENGTH=0.000
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X      33.580                                     33.593      0.013
TP        RFS      0.060                 0.000      0.026      0.026      0.000 ---#-----

## <G-V7>
DIM PERP5= PERPENDICULARITY OF CYLINDER CYL_C,RFS TO PLANE PLN  _K,RFS EXTENDLENGTH=0.000
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.200      0.000      0.009      0.009      0.000 #--------

## <G-F9>
DIM LOC63= POSITION OF PLANE PLN  _K
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z       1.510                                      1.492     -0.018
TP        RFS      0.300                 0.000      0.036      0.036      0.000 -#-------

## <G-F5>
DIM LOC64= LOCATION OF CIRCLE D4.1
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        4.100      0.050     -0.050      4.079     -0.021      0.000 --#------

## <G-F11>
DIM CONCEN9= CONCENTRICITY FROM CIRCLE D4.1 TO CYLINDER CYL_C
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.100      0.000      0.019      0.019      0.000 -#-------
```

```
### Section view J-J
## <J-V19>
DIM LOC114= LOCATION OF CIRCLE D31.56_AB
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       31.560      0.200     -0.200     31.686      0.126      0.000 -------#-

## <J-F20>
DIM CONCEN14= CONCENTRICITY FROM CIRCLE D31.56_AB TO CYLINDER CYL_D11.1_E
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.300      0.000      0.139      0.139      0.000 ----#----

## <J-F23>
DIM LOC115= LOCATION OF CIRCLE D31.8
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       31.800      0.200     -0.200     31.914      0.114      0.000 -------#-

## <J-F24>
DIM CONCEN13= CONCENTRICITY FROM CIRCLE D31.8 TO CIRCLE D31.56_AB
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.200      0.000      0.021      0.021      0.000 #--------

## <J-F10>
DIM LOC69= POSITION OF PLANE PLN  _L
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z       3.960                                      3.914     -0.046
TP        RFS      0.300                 0.000      0.092      0.092      0.000 --#------

## <J-V2>
DIM LOC65= LOCATION OF CYLINDER CYL_D11.1_E
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       11.100      0.028      0.010     11.118      0.018      0.000 ---#-----

## <J-V13>
DIM LOC66= POSITION OF CYLINDER CYL_D11.1_E  USE AXIS=AVERAGE  REF LENGTH=0.000
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X      24.690                                     24.661     -0.029
TP        RFS      0.060                 0.000      0.057      0.057      0.000 --------#

## <J-F14>
DIM PERP6= PERPENDICULARITY OF CYLINDER CYL_D11.1_E,RFS TO PLANE PLN  _L,RFS EXTENDLENGTH=0.000
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.150      0.000      0.004      0.004      0.000 #--------

## <J-F11>
DIM LOC68= POSITION OF PLANE PLN  _AF
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z     -46.950                                    -46.999     -0.049
TP        RFS      0.300                 0.000      0.099      0.099      0.000 --#------

## <J-F21>
DIM LOC67= POSITION OF POINT PNT_8.2
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      -8.200                                     -8.242     -0.042
TP        RFS      0.300                 0.000      0.084      0.084      0.000 --#------


### Section view L-L
## <L-F1> (x2)
## T1
DIM LOC70= LOCATION OF CYLINDER CYL_D3.7_L1
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        3.700      0.050     -0.050      3.724      0.024      0.000 ------#--

## T2
DIM LOC71= LOCATION OF CYLINDER CYL_D3.7_L2_Z
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        3.700      0.050     -0.050      3.730      0.030      0.000 -------#-
```

```
## <L-F6> (x2)
## T1
DIM LOC72= POSITION OF CYLINDER CYL_D3.7_L1  USE AXIS=AVERAGE  REF LENGTH=0.000
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
PR     21.500                                      21.479     -0.021
PA    287.000                                     286.935     -0.065
TP        RFS      0.200                 0.000      0.064      0.064      0.000 --#------

## T2
DIM LOC73= POSITION OF CYLINDER CYL_D3.7_L2_Z  USE AXIS=AVERAGE  REF LENGTH=0.000
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
PR     21.500                                      21.509      0.009
PA     92.000                                      92.001      0.001
TP        RFS      0.200                 0.000      0.018      0.018      0.000 #--------

## <L-F2> (x2)
## T1
DIM LOC74= LOCATION OF CIRCLE D4.7_L1
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        4.700      0.100     -0.100      4.729      0.029      0.000 -----#---

## T2
DIM LOC75= LOCATION OF CIRCLE D4.7_L2
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
Z       -1.000      0.100     -0.100     -1.000      0.000      0.000 ----#----
D        4.700      0.100     -0.100      4.725      0.025      0.000 -----#---

## <L-F7> (x2)
## T1
DIM CONCEN10= CONCENTRICITY FROM CIRCLE D4.7_L1 TO CYLINDER CYL_D3.7_L1
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.200      0.000      0.034      0.034      0.000 -#-------

## T2
DIM CONCEN11= CONCENTRICITY FROM CIRCLE D4.7_L2 TO CYLINDER CYL_D3.7_L2_Z
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.200      0.000      0.001      0.001      0.000 #--------


### Detail K
## <K-F4> (x2)
DIM LOC76= POSITION OF POINT PNT_8.3_1
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y       8.030                                       8.042      0.012
TP        RFS      0.600                 0.000      0.023      0.023      0.000 #--------

DIM LOC77= POSITION OF POINT PNT_8.3_2
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y       8.030                                       8.046      0.016
TP        RFS      0.600                 0.000      0.031      0.031      0.000 #--------

## <K-F13> (x2)
DIM LOC78= POSITION OF POINT PNT_9.89_1
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y      -9.890                                      -9.848      0.042
TP        RFS      0.600                 0.000      0.084      0.084      0.000 -#-------

DIM LOC79= POSITION OF POINT PNT_9.89_2
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y      -9.890                                      -9.817      0.073
TP        RFS      0.600                 0.000      0.146      0.146      0.000 --#------


### Section view BC-BC
## <BE-F1>
DIM LOC80= LOCATION OF CYLINDER CYL_D3.98_D
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        3.980      0.050     -0.050      3.972     -0.008      0.000 ---#-----
```

```
## <BE-F2>
DIM LOC81= POSITION OF CYLINDER CYL_D3.98_D  USE AXIS=AVERAGE  REF LENGTH=0.000
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
PR     61.870                                       61.893      0.023
PA    159.000                                      159.032      0.032
TP        RFS      0.100                 0.000      0.083      0.083      0.000 -------#-

## <BE-F3>
DIM PERP7= PERPENDICULARITY OF CYLINDER CYL_D3.98_D,RFS TO PLANE PLN  _A,RFS EXTENDLENGTH=0.000
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.350      0.000      0.005      0.005      0.000 #--------

## <BE-F6>
DIM LOC110= POSITION OF PLANE PLN  _0.7
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      -0.700                                      -0.738     -0.038
TP        RFS      0.400                 0.000      0.076      0.076      0.000 -#-------


### Section view S-S
## <S-F5> (x2)
## (16.45)
DIM LOC82= POSITION OF POINT PNT_16.45_1
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      16.450                                      16.462      0.012
TP        RFS      0.500                 0.000      0.024      0.024      0.000 #--------

DIM LOC83= POSITION OF POINT PNT_16.45_2
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      16.450                                      16.462      0.012
TP        RFS      0.500                 0.000      0.024      0.024      0.000 #--------

## (18.255)
DIM LOC84= POSITION OF POINT PNT_18.255_1
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      18.225                                      18.233      0.008
TP        RFS      0.500                 0.000      0.016      0.016      0.000 #--------

DIM LOC85= POSITION OF POINT PNT_18.255_2
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      18.225                                      18.227      0.002
TP        RFS      0.500                 0.000      0.003      0.003      0.000 #--------

## <S-F6>
DIM LOC86= POSITION OF POINT PNT_15.81_1
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
PR     15.810                                      15.707     -0.103
TP        RFS      0.600                 0.000      0.216      0.216      0.000 ---#-----

DIM LOC87= POSITION OF POINT PNT_15.81_2
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
PR     15.810                                      15.698     -0.112
TP        RFS      0.600                 0.000      0.232      0.232      0.000 ---#-----

## <S-F7>
DIM LOC88= POSITION OF POINT PNT_18.08_1
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
PR     18.080                                      17.935     -0.145
TP        RFS      0.600                 0.000      0.311      0.311      0.000 ----#----

DIM LOC89= POSITION OF POINT PNT_18.08_2
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
PR     18.080                                      17.939     -0.141
TP        RFS      0.600                 0.000      0.303      0.303      0.000 ----#----
```

```
### Section view AJ-AJ
## <AJ-F1> (x2)
DIM LOC91= POSITION OF POINT PNT_28.445_2
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      28.445                                      28.398     -0.047
TP        RFS      0.500                 0.000      0.095      0.095      0.000 -#-------

DIM LOC92= POSITION OF POINT PNT_28.445_2
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      28.445                                      28.401     -0.044
TP        RFS      0.500                 0.000      0.088      0.088      0.000 -#-------

## <AJ-F4>
DIM LOC90= LOCATION OF CIRCLE D44.42
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       44.420      0.200     -0.200     44.529      0.109      0.000 ------#--

## <AJ-F5>
DIM CONCEN12= CONCENTRICITY FROM CIRCLE D44.42 TO LINE LIN_B
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.500      0.000      0.127      0.127      0.000 --#------


### Section view R-R
## <R-F6> (x2)
DIM LOC93= POSITION OF POINT PNT_33.395_1
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      33.395                                      33.346     -0.049
TP        RFS      0.400                 0.000      0.098      0.098      0.000 --#------

DIM LOC94= POSITION OF POINT PNT_33.395_2
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      33.395                                      33.349     -0.046
TP        RFS      0.400                 0.000      0.092      0.092      0.000 --#------

## <R-F5>
DIM LOC95= POSITION OF POINT PNT_34.545
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      34.545                                      34.518     -0.027
TP        RFS      0.400                 0.000      0.054      0.054      0.000 -#-------

## <R-F4>
DIM LOC96= POSITION OF PLANE PLN  _M
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      12.700                                      12.647     -0.053
TP        RFS      0.400                 0.000      0.106      0.106      0.000 --#------


### Detail Q
## <Q-F6> (x2)
DIM PROF1= PROFILE OF SURFACE OF SET SCN_<Q-F6>_1    FORMANDLOCATION
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.400      0.000      0.183      0.183      0.000 ----#----

DIM PROF2= PROFILE OF SURFACE OF SET SCN_<Q-F6>_2    FORMANDLOCATION
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.400      0.000      0.070      0.070      0.000 -#-------

## <Q-F14>
DIM PROF3= PROFILE OF SURFACE OF SET SCN_<Q-F14>    FORMANDLOCATION
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.400      0.000      0.107      0.107      0.000 --#------

## <Q-F9> (x3)
DIM LOC97= POSITION OF POINT PNT<Q-F9>_1
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y       0.000                                      -0.049     -0.049
TP        RFS      0.500                 0.000      0.098      0.098      0.000 -#-------
```

```
DIM LOC98= POSITION OF POINT PNT<Q-F9>_2
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y       0.000                                       -0.054     -0.054
TP        RFS      0.500                 0.000       0.108      0.108      0.000 -#-------

DIM LOC99= POSITION OF POINT PNT<Q-F9>_3
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y       0.000                                       -0.055     -0.055
TP        RFS      0.500                 0.000       0.110      0.110      0.000 -#-------

## <Q-V12> (x3)
DIM LOC100= POSITION OF POINT PNT<Q-V12>_1
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y      -1.000                                       -0.961      0.039
TP        RFS      0.250                 0.000       0.078      0.078      0.000 --#------

DIM LOC101= POSITION OF POINT PNT<Q-V12>_2
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y      -1.000                                       -0.967      0.033
TP        RFS      0.250                 0.000       0.065      0.065      0.000 --#------

DIM LOC102= POSITION OF POINT PNT<Q-V12>_3
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y      -1.000                                       -0.962      0.038
TP        RFS      0.250                 0.000       0.077      0.077      0.000 --#------

## <Q-F3> (x4)
DIM LOC103= POSITION OF POINT PNT<Q-F3>_1
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y      -0.900                                       -0.855      0.045
TP        RFS      0.500                 0.000       0.091      0.091      0.000 -#-------

DIM LOC104= POSITION OF POINT PNT<Q-F3>_2
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y      -0.900                                       -0.852      0.048
TP        RFS      0.500                 0.000       0.096      0.096      0.000 -#-------

DIM LOC105= POSITION OF POINT PNT<Q-F3>_3
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y      -0.900                                       -0.848      0.052
TP        RFS      0.500                 0.000       0.103      0.103      0.000 -#-------

DIM LOC106= POSITION OF POINT PNT<Q-F3>_4
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y      -0.900                                       -0.857      0.043
TP        RFS      0.500                 0.000       0.086      0.086      0.000 -#-------

## <Q-V8> (x3)
DIM LOC107= POSITION OF POINT PNT<Q-V8>_1
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y       0.000                                       -0.027     -0.027
TP        RFS      0.500                 0.000       0.054      0.054      0.000 #--------

DIM LOC108= POSITION OF POINT PNT<Q-V8>_2
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y       0.000                                       -0.027     -0.027
TP        RFS      0.500                 0.000       0.053      0.053      0.000 #--------

DIM LOC109= POSITION OF POINT PNT<Q-V8>_3
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y       0.000                                       -0.041     -0.041
TP        RFS      0.500                 0.000       0.082      0.082      0.000 -#-------
```