Well	KN-121	**Rig**	Rig KD-7	**Report no**	4	**Date**	2022-04-14
Hole size	17½ in	**Depth 00:00**	518.5 m MD	**Depth 24:00**	654.1 m MD	**TVD 24:00**	654.1 m
Spud date	2022-04-11	**Days from spud**	4	**RT elevation**	117 m	**Field**	Kathal Nala

24 H SUMMARY

Drilled 17½ in hole from 519 m to 654 m, 136 m. NPT 14.3 h: bit balling in sticky clay; bit balling in sticky clay; tight hole on trip.

24 H FORECAST

Drill ahead 17½ in hole.

OPERATIONS

From	To	Hrs	Code	Depth m	Operation
00:00	01:18	1.30	DRL	537.5	Drilled 17½ in hole from 519 m to 538 m, avg ROP 14.5 m/h. WOB 17 t, 128 rpm, 850 gpm. Connections and MWD surveys each stand.
01:18	03:18	2.00	NPT	537.5	ROP fell to 5 m/h with low torque, bit balled in sticky clay.
03:18	06:30	3.20	NPT	537.5	Pumped a detergent sweep and raised flow. ROP recovered.
06:30	11:06	4.59	DRL	598.5	Drilled 17½ in hole from 538 m to 599 m, avg ROP 13.3 m/h. WOB 17 t, 128 rpm, 850 gpm. Connections and MWD surveys each stand.
11:06	12:40	1.56	DRL	622.5	Drilled 17½ in hole from 599 m to 623 m, avg ROP 15.4 m/h. WOB 17 t, 128 rpm, 850 gpm. Connections and MWD surveys each stand.
12:40	13:40	1.00	NPT	622.5	ROP fell to 3 m/h with low torque, bit balled in sticky clay.
13:40	16:10	2.50	NPT	622.5	Pumped a detergent sweep and raised flow. ROP recovered.
16:10	18:23	2.22	DRL	654.1	Drilled 17½ in hole from 623 m to 654 m, avg ROP 14.2 m/h. WOB 17 t, 128 rpm, 850 gpm. Connections and MWD surveys each stand.
18:23	20:53	2.50	NPT	654.1	Overpull of 12 t at 654 m while pulling out of hole.
20:53	24:00	3.12	NPT	654.1	Worked through with back-reaming and circulated the hole clean.

INCIDENTS AND NPT

INCIDENT KN-121-B01 | BIT BALLING
Title: Bit balling in sticky clay
Start: 01:18 **Depth:** 537.5 m MD **MW:** 9.6 ppg **NPT:** 5.2 h
Description: ROP fell to 5 m/h with low torque, bit balled in sticky clay.
Action: Pumped a detergent sweep and raised flow. ROP recovered.
Remarks: Run a detergent sweep every 150 m in the Girujan.

INCIDENT KN-121-B02 | BIT BALLING
Title: Bit balling in sticky clay
Start: 12:40 **Depth:** 622.5 m MD **MW:** 9.6 ppg **NPT:** 3.5 h
Description: ROP fell to 3 m/h with low torque, bit balled in sticky clay.
Action: Pumped a detergent sweep and raised flow. ROP recovered.
Remarks: Run a detergent sweep every 150 m in the Girujan.

INCIDENT KN-121-B03 | TIGHT HOLE
Title: Tight hole on trip
Start: 18:23 **Depth:** 654.1 m MD **MW:** 9.6 ppg **NPT:** 7.2 h
Description: Overpull of 12 t at 654 m while pulling out of hole.
Action: Worked through with back-reaming and circulated the hole clean.
Remarks: Back-ream stands through the Girujan on every trip.

MUD PROPERTIES

Type	Mud weight	Funnel vis	PV	YP	Fluid loss
WBM, PHPA	9.6 ppg	48 s	21 cP	17 lb/100 ft²	4.6 ml

BIT RECORD

Bit no	Size	Type	Depth in	Metres	Hours
2	17½ in	PDC, 6 blade	309.6 m	344.5	49.6

SURVEYS

MD m	Inc deg	Azi deg	TVD m
540.0	0.00	197.9	540.0
570.0	0.14	199.1	570.0
600.0	0.09	202.1	600.0

MD m	Inc deg	Azi deg	TVD m
630.0	0.01	200.8	630.0