


(a) Four settings



—○— No null-space torque

—◇— Conditioning, $k_{\sigma} = 2$ N m

—□— Damping, $d_{\text{null}} = 2$ N m s/rad

—▽— Combined, $k_{\sigma} = 2, d_{\text{null}} = 2$

Three-trial mean and one sample standard deviation.

(b) Conditioning and combined

