

$$N_\tau = I_7 - J^T J^+{}^T, \quad \tau_{\text{null}} = \tau_d + \tau_\sigma$$