

Title slide | Opening

Hello everyone, and thank you for being here.

Today, I will present my work on controlling a seven-joint robot for grinding. The main goal is to help the tool align with a surface and to reduce unwanted motion of the robot arm.

Slide 1 | Motivation

First, let me explain why tool alignment is important.

For grinding, the tool face needs to be properly aligned with the surface. However, in practice, the exact angle of the real surface is not always known. This means that the surface used by the controller may be slightly different from the actual surface. Moreover, joint friction can also affect the orientation of the tool. The controller therefore allows the tool to rotate passively during contact, which helps it align with the real surface. This video shows the basic idea.

[Play the full video: about 51 seconds. Then say:]

As you can see, the tool rotates even though its desired orientation remains fixed.

Slide 2 | Overview

First, I will give you a short overview of the presentation.

I will start by explaining the controller. Then, I will show the contact experiments and their results. After that, I will discuss the extra joint motion and the null-space controller. Finally, I will summarize the main findings.

Slide 3 | Cartesian pose

I will start with how we describe the tool.

The pose of the tool consists of its position and orientation. In other words, it tells us where the tool is and how it is rotated. We use three coordinates for the position and three coordinates for the orientation. Using forward kinematics, we calculate the tool pose from all seven joint angles of the robot.

Slide 4 | Surface frame

Now, we can describe the surface around the tool.

The normal direction points out of the surface, while the two tangent directions lie along the surface. These directions define the force and moment components. They also determine in which directions the tool should be compliant and in which directions it should remain stiff.

Slide 5 | Cartesian impedance law

To control this behaviour, I use Cartesian impedance control.

The basic idea is similar to a spring and a damper. The spring pulls the tool towards its desired pose, while the damping slows down the motion. A position error creates a force, and an orientation error creates a turning moment. Together, the force and moment are called a wrench. An important point here is that the translational and rotational behaviour can be adjusted separately.

Slide 6 | Real-time control

To apply this control law, we need to calculate the torques for the robot joints.

The Jacobian transpose converts the Cartesian wrench into joint torques. We then add Coriolis compensation and the posture-control torques, which I will explain later. However, gravity compensation is handled internally by the robot. The complete control loop runs every millisecond using the latest measured robot state.

Slide 7 | Centre of compliance: a virtual reference

Next, we can change how the force affects the rotation of the tool.

The tool centre point, or TCP, is our controlled point on the end effector, or EE. The centre of compliance, or CoC, is a virtual reference point used for stiffness and damping. If we shift the CoC away from the TCP, the applied force creates an additional moment around the TCP.

Slide 8 | Supporting and opposing CoC shifts

This CoC shift can help the alignment, but it can also work against it.

On the left, the additional moment supports the alignment. On the right, the additional moment opposes the alignment. This means that the direction of the CoC shift has to match the initial angular offset of the tool.

Slide 9 | Translation-rotation coupling

The equations on this slide describe this connection.

We use the shift between the TCP and the CoC to transform the stiffness and damping. This creates new terms that connect translation and rotation. As a result, a force that presses the tool against the surface can also create a turning effect.

Slide 10 | Contact experiment

With the controller defined, I can now show the contact experiment.

I deliberately start the tool with an angular offset. This represents the mismatch between the surface orientation used by the controller and the real surface orientation. The robot then approaches the surface, makes contact and performs the grinding motion. Motion in the normal direction and rotation about the two tangent axes are compliant. The other directions remain stiff.

Slide 11 | Plausibility experiment

Before looking at the alignment results, I first checked the basic response of the controller.

For this test, I pushed and rotated the tool by hand, as shown in the video.

[Play the full video: about 14 seconds. Then say:]

The next two plots compare the commanded and estimated values with the values predicted by the spring equation. It is important to note that the estimated values are model-based measurements.

Slide 12 | Force plausibility

Let us first look at the force.

A displacement of about twenty millimetres gives a predicted force of approximately minus twenty newtons. The commanded mean is almost the same, while the model estimate is slightly larger. The two values shown below the plot are mean values calculated over the shaded steady-state interval.

Slide 13 | Moment plausibility

Next, I repeated the same check for rotation.

A rotation of approximately six and a half degrees gives predicted and commanded mean moments of about one point seven newton metres. The estimated mean is slightly higher. Again, these values are calculated over the shaded interval. Overall, both tests support the expected spring behaviour of the controller.

Slide 14 | Moment during contact alignment

Now, let us look at what happens during actual contact alignment.

In this separate test, the force curves remain close to each other. However, the model-estimated moment is larger during the alignment motion. It includes the contact moment from the surface, which helps turn the tool towards alignment. Once the motion settles, the values become close again.

Slide 15 | Effect of rotational stiffness

To understand this turning behaviour better, I first changed the rotational stiffness.

The plot shows the remaining angular error relative to the calibrated surface. A value closer to zero means better alignment in this direction. We can see that a higher rotational stiffness leaves a larger remaining error. This happens because the higher stiffness resists rotation during contact.

Slide 16 | CoC shift and entry offset

Next, I changed the centre of compliance.

For a positive starting offset, a positive CoC shift helps the alignment. For a negative starting offset, a different CoC position is more useful. This also shows that a larger shift is not always better. The direction and size of the CoC shift have to match the initial angular offset.

Slide 17 | Turning response over time

Here, we can see the same effect over time.

The supporting CoC shift helps the alignment happen faster. The opposing CoC shift leaves much of the initial angular error. The normal forces are broadly similar between the different cases, but the moments are different. This means that the CoC mainly changes the rotational response of the tool.

Slide 18 | Null-space controller

Next, I will explain the null-space controller.

The robot has seven joints, but only six coordinates are needed to describe the tool pose. This gives the robot one extra degree of freedom. Because of this extra freedom, the arm can change its posture while keeping the tool pose almost unchanged. I added two additional torque terms: a damping torque and a conditioning torque. Damping is based on joint velocity, while conditioning is based on joint position. The damping torque opposes this extra joint motion. The conditioning torque tries to achieve a larger minimum singular value of the Jacobian, which we call sigma min. A larger sigma min helps the robot avoid postures where certain tool movements become difficult.

Slide 19 | Control OFF, then damping ON

Let me first show what the damping torque does.

This video starts with the null-space controller switched off. Then, the damping torque is switched on.

[Play the full video: about 23 seconds. Then say:]

With null-space control off, the arm moves more easily. With damping on, the same push moves the arm more slowly. I need to push harder to move it at the same speed. The main controller still holds the tool pose.

Slide 20 | Conditioning ON

Now, let us compare this with conditioning.

In this video, the conditioning controller is active.

[Play the full video: about 8 seconds. Then say:]

The purpose of conditioning is different from damping. Conditioning tries to improve the posture of the robot while keeping the tool pose. Damping, on the other hand, mainly opposes unnecessary motion.

Slide 21 | Null-space experiment

To compare these effects, I used the same disturbance in each experiment.

The disturbance is created using joint torques that represent a virtual force of twenty newtons acting on joint three. I tested four different cases: no null-space control, damping only, conditioning only, and damping together with conditioning. Each case was tested three times. Joint one is shown because it receives the largest peak disturbance torque. The following plots show the mean results from the three trials over four seconds.

Slide 22 | Joint motion over time

Let us first look at how much joint one moves.

Damping reduces the motion. Conditioning and the combined controller keep the motion much smaller. The plot on the right shows a zoomed view. We can see that the joint changes direction several times. Adding damping reduces the total amount of motion, although some reversals still remain.

Slide 23 | Jacobian conditioning

Reducing the joint motion is useful, but we also need to check the posture of the robot.

For this, we look at sigma min. Without null-space control, sigma min decreases. The same happens when only damping is used. With conditioning, either alone or combined with damping, sigma min stays almost constant. This shows that damping and conditioning have different roles. Damping mainly limits unnecessary motion, while conditioning helps maintain the Jacobian conditioning.

Slide 24 | Conclusion

These results bring me to the main conclusions.

Allowing the tool to rotate during contact helps reduce the angular error. The centre of compliance can support the alignment, but it can also oppose it if the direction is not chosen correctly. A higher rotational stiffness resists rotation more strongly and therefore leaves a larger angular error. The null-space controller helps reduce unwanted motion of the robot arm. Damping and conditioning have different roles and can also be combined.

As future work, I would improve the mechanical tool mount. I would also adjust the centre of compliance during the alignment process and then return it to the TCP once the alignment is complete. Thank you for your attention. I am happy to take your questions.

[End of the main talk. Use backups only if needed for questions.]

Use only the relevant backup when answering a question. These six scripts are outside the 15-minute main talk. Each can be read on its own.

Backup B1 | Opposing moment

This extra video shows why the direction of the CoC shift matters.

Here, the added moment acts against alignment.

[Play the full video: about 10 seconds. Then say:]

This is the opposing case from the earlier diagrams. It shows that a shift can hinder the turning motion. The result plots give the numerical comparison.

Backup B2 | Null-space torques and projector

This slide gives more detail about the two null-space torques.

The projector selects directions for the secondary torque while preserving the main tool-pose task. Damping opposes the projected joint velocity and is zero when the joints stop. Conditioning chooses the direction with a better sigma min and can act at rest. A small deadband avoids unnecessary changes.

Backup B3 | Angular quantities

To make the angle measurement clear, let us look at this diagram.

The red arc is the angular offset at contact entry. The blue arc is the remaining angular error. Both use the calibrated surface as their reference. The plotted error is the component about the first surface tangent. Zero in this one component does not guarantee perfect physical alignment.

Backup B4 | Baseline angular error

This is the baseline result with the CoC at the TCP.

Contact reduces the two large starting offsets, but a small angular error remains. The three final errors are around one and a half degrees. Friction, calibration and the tool mount may contribute. This comparison does not separate those causes.

Backup B5 | Sources of angular offset

This diagram explains two sources of angular mismatch.

The real surface may differ from the surface used in the controller. Also, the actual tool orientation may differ from the desired orientation. The green line shows the tool face, and the dashed line shows the desired orientation. Both differences affect the angle at contact entry. We use a deliberate angular offset to represent this mismatch in the contact tests.

Backup B6 | Cumulative joint motion

This last comparison looks at total motion across all seven joints.

It adds up motion over time, so changes of direction do not cancel. Damping alone gives about twenty-five percent less motion than no null-space torque. Adding damping to conditioning gives about fifty percent less than conditioning alone, at a conditioning setting of two newton metres.