



(a) Four settings



(b) Conditioning and combined
First second



- No null-space torque —□— Damping, $d_{\text{null}} = 2 \text{ N m s/rad}$
—◇— Conditioning, $k_{\sigma} = 2 \text{ N m}$ —▽— Combined, $k_{\sigma} = 2, d_{\text{null}} = 2 \text{ (SI)}$

Three-trial mean and one sample standard deviation.