


(a) All settings



—○— No null-space torque

—△— Conditioning, $k_\sigma = 1.5$ N m—◆— Combined, $k_\sigma = 1.5$, $d_{\text{null}} = 2$ (SI)—□— Damping, $d_{\text{null}} = 2$ N m s/rad—◇— Conditioning, $k_\sigma = 2$ N m—▽— Combined, $k_\sigma = 2$, $d_{\text{null}} = 2$ (SI)(b) Conditioning and combined
First second