



(a) All settings



(b) Conditioning and combined



—○— No null-space torque

—△— Conditioning, $k_\sigma = 1.5$ N m

—◆— Combined, $k_\sigma = 1.5$, $d_{\text{null}} = 2$ (SI)

—□— Damping, $d_{\text{null}} = 2$ N m s/rad

—◇— Conditioning, $k_\sigma = 2$ N m

—▽— Combined, $k_\sigma = 2$, $d_{\text{null}} = 2$ (SI)