

Title slide | Opening

Hello everyone, and thank you for being here.

Today I will present my work on controlling a seven-joint robot for grinding. The aim is to help the tool align with a surface and reduce unwanted arm motion.

Slide 1 | Motivation

First, let me explain why tool alignment matters.

Grinding needs an aligned tool face. In practice, the real surface angle is not known exactly. So the surface used in the controller may not match the real surface. Joint friction can also affect the tool orientation. I let the tool give way in rotation, so contact helps alignment. This video shows the idea.

[Play the full video: about 51 seconds. Then say:]

The tool turns even though its desired orientation stays fixed.

Slide 2 | Overview

First, I will give you a short overview of my presentation.

I will explain the controller, then show the contact tests and results. After that, I will discuss the extra joint motion and finish with the main findings.

Slide 3 | Cartesian pose

I will start with how we describe the tool.

Pose means position and orientation: where the tool is and how it is turned. We use three coordinates for each. Forward kinematics calculates the pose from all seven joint angles.

Slide 4 | Surface frame

Now we can describe the surface around the tool.

The normal points out of the surface. The two tangents lie along it. These directions define the force and moment components and where the tool should give way or stay stiff.

Slide 5 | Cartesian impedance law

To control this behaviour, I use impedance control.

It acts like a spring and a damper. The spring pulls towards the desired pose; damping slows motion. Position error creates force, and rotation error creates a turning moment. Together, force and moment are called a wrench. Here, translation and rotation are set separately.

Slide 6 | Real-time control

To apply this law, we need torques at the robot joints.

The Jacobian transpose converts the wrench into joint torques. We add Coriolis compensation and the posture-control torques, which I will explain later. Gravity compensation happens inside the robot. This loop runs every millisecond, using the latest measured state.

Slide 7 | Centre of compliance: a virtual reference

Next, we can change how the force turns the tool.

The tool centre point, or TCP, is our controlled point. The centre of compliance, or CoC, is a virtual reference for stiffness and damping. Shifting it adds a moment about the TCP. This does not move the physical contact point.

Slide 8 | Supporting and opposing CoC shifts

This shift can help alignment, but it can also work against it.

On the left, the added moment supports alignment. On the right, it opposes alignment. The shift direction must match the starting angular offset.

Slide 9 | Translation-rotation coupling

The equations here describe this connection.

We use the shift from the TCP to the CoC to transform stiffness and damping. The new terms connect translation and rotation. A pressing force can therefore also create a turning effect.

Slide 10 | Contact experiment

With the controller defined, I can now show the contact experiment.

I deliberately start the tool with an angular offset. This represents the mismatch between the surface used in the controller and the real surface. The robot then approaches, makes contact, and grinds. Normal motion and rotations about the tangents give way. The other directions stay stiff.

Slide 11 | Plausibility experiment

Before looking at alignment, I checked the basic response.

I pushed and turned the tool by hand, as shown here.

[Play the full video: about 14 seconds. Then say:]

The next two plots compare the commanded and estimated values with the spring calculation.

Slide 12 | Force plausibility

Let us look first at the force.

A push of about twenty millimetres gives a predicted force of about minus twenty newtons. The commanded mean is almost the same. The model estimate is slightly stronger. All three values below the plot are means over the shaded, steady interval.

Slide 13 | Moment plausibility

Next, I repeat the same check for rotation.

About six and a half degrees gives predicted and commanded mean moments of about one point seven newton metres. The estimated mean is slightly higher. Again, these means cover the shaded interval. Both tests support the expected spring response.

Slide 14 | Moment during contact alignment

This leads to what happens during actual contact.

In this separate test, the force curves stay close, but the estimated moment is larger during alignment. This is consistent with contact helping to turn the tool. Once the motion settles, the values become close.

Slide 15 | Effect of rotational stiffness

To understand this turning motion, I first changed the rotational stiffness.

The plot shows the remaining angular error relative to the calibrated surface. Closer to zero means better alignment in this direction. Higher stiffness leaves more error because it resists rotation during contact.

Slide 16 | CoC shift and entry offset

I then changed the centre of compliance.

For a positive starting offset, a positive CoC shift helps alignment. For a negative offset, the useful position is different. A larger shift is not always better. Its direction and size must suit the starting offset.

Slide 17 | Turning response over time

Here, we can see that effect over time.

The supporting shift helps alignment happen faster. The opposing shift leaves much of the initial angular error. Normal forces are broadly similar, but moments differ. So the CoC mainly changes the turning response.

Slide 18 | Null-space controller

That completes the contact results. I will now turn to extra arm motion.

Seven joints control six tool-pose coordinates. The extra freedom lets the arm change posture while holding the tool pose. Damping opposes this extra motion. Conditioning seeks a larger minimum singular value, called sigma min. This helps avoid postures where some tool movements become difficult.

Slide 19 | Control OFF, then damping ON

Let me first show what damping does.

This video starts with null-space control off. Then damping is switched on.

[Play the full video: about 23 seconds. Then say:]

Damping opposes the extra arm motion while the main controller holds the tool pose.

Slide 20 | Conditioning ON

Now, let us compare this with conditioning.

Here, conditioning is on.

[Play the full video: about 8 seconds. Then say:]

It aims to improve the arm posture while holding the tool pose. Its purpose differs from damping, which opposes motion.

Slide 21 | Null-space experiment

To compare these effects, I used the same disturbance in each test.

Joint torques represent a virtual twenty-newton force on link three. I tested no null-space control, damping, conditioning, and both together, with three trials each. Joint one is shown because it receives the largest peak disturbance torque. The next plots show trial means over four seconds.

Slide 22 | Joint motion over time

Let us start with how much joint one moves.

Damping reduces the motion. Conditioning and combined control keep it much smaller. The right plot zooms in: the joint changes direction several times. Adding damping reduces total motion, but some reversals remain.

Slide 23 | Jacobian conditioning

Less motion is useful, but we also need to check the arm posture.

Sigma min falls with no null-space control and with damping alone. With conditioning, alone or combined with damping, it stays nearly constant. So damping mainly limits motion, while conditioning helps maintain this measure.

Slide 24 | Conclusion

These results bring me to the main conclusions.

Allowing rotation helps contact reduce angular error. The CoC can help or oppose alignment, while higher stiffness resists rotation. Null-space control reduces unwanted arm motion. Damping and conditioning have different roles. Next, I would improve the tool mount and adjust the CoC during alignment, then return it to the TCP. Thank you for your attention. I am happy to take your questions.

[End of the main talk. Use backups only if needed for questions.]

Use only the relevant backup when answering a question. These six scripts are outside the 15-minute main talk. Each can be read on its own.

Backup B1 | Opposing moment

This extra video shows why the direction of the CoC shift matters.

Here, the added moment acts against alignment.

[Play the full video: about 10 seconds. Then say:]

This is the opposing case from the earlier diagrams. It shows that a shift can hinder the turning motion. The result plots give the numerical comparison.

Backup B2 | Null-space torques and projector

This slide gives more detail about the two null-space torques.

The projector selects directions for the secondary torque while preserving the main tool-pose task. Damping opposes the projected joint velocity and is zero when the joints stop. Conditioning chooses the direction with a better sigma min and can act at rest. A small deadband avoids unnecessary changes.

Backup B3 | Angular quantities

To make the angle measurement clear, let us look at this diagram.

The red arc is the angular offset at contact entry. The blue arc is the remaining angular error. Both use the calibrated surface as their reference. The plotted error is the component about the first surface tangent. Zero in this one component does not guarantee perfect physical alignment.

Backup B4 | Baseline angular error

This is the baseline result with the CoC at the TCP.

Contact reduces the two large starting offsets, but a small angular error remains. The three final errors are around one and a half degrees. Friction, calibration and the tool mount may contribute. This comparison does not separate those causes.

Backup B5 | Sources of angular offset

This diagram explains two sources of angular mismatch.

The real surface may differ from the surface used in the controller. Also, the actual tool orientation may differ from the desired orientation. The green line shows the tool face, and the dashed line shows the desired orientation. Both differences affect the angle at contact entry. We use a deliberate angular offset to represent this mismatch in the contact tests.

Backup B6 | Cumulative joint motion

This last comparison looks at total motion across all seven joints.

It adds up motion over time, so changes of direction do not cancel. Damping alone gives about twenty-five percent less motion than no null-space torque. Adding damping to conditioning gives about fifty percent less than conditioning alone, at a conditioning setting of two newton metres.