

SPRINGFIELD NUCLEAR POWER PLANT
Emergency Shutdown Procedure (SOP-114)

Revision 7 - Safety & Compliance

1. Scope

This procedure covers the manual reactor scram, the conditions that require it, and the verification steps that follow.

2. Scram thresholds

A manual scram is required as soon as any of the following is observed:

- Primary coolant temperature reaches 315 degrees Celsius.
- Coolant flow drops below 60 percent of nominal for more than 30 seconds.
- Containment pressure exceeds 1.4 bar.

The shift supervisor may not defer a scram once a threshold is reached, regardless of the expected duration of the excursion.

3. Verification

After the control rods are fully inserted, log the trip time, the triggering threshold, and the coolant temperature at insertion in the shift record. Notify the NRC resident inspector within one hour.