Honeywell Int. SDN BHD 161 Gul Circle Singapore 629619

Quote Number: 226129716 Version 1 **Service Order:** 5018461991 Validity Period: 05/26/2024 to 06/05/2024

Customer PO: HA70762224 Part Number: Primary Workscope: OVERHAUL 3800708-1 Sales order: 552002730 Serial In: P-8113 Notification: 349735780

CUSTOMER INFORMATION

VIETNAM AIRLINES JSC

200 NGUYEN SON STR 10000 HANOI-LONGBEIN **VIETNAM**

WARRANTY DETAILS

WARRANTY NOT APPLICABLE Warranty Result:

Adjudication:

ORDER INFORMATION

Model Number Out: TAT Days: 45 Days Serial Number Out: P-8113 **Currency:** USD Part Number Out: 3800708-1 Exchange Rate: 1.00000

Part Desc: ENGINE OUTLINE, GAS TURBINE

QUOTE TOTALS	
APU/Engine Labor & Test	\$ 8,403.20
New/Replaced Parts	\$ 532,429.30
Repair & Overhaul Parts	\$ 264,433.68
Consumables/Line Stock	\$ 3,072.77
SUB-TOTALS	\$ 808,338.95
NTE Reduction:	\$ -(454,738.95)
NTE:	\$ 353,600.00
Over & Above:	\$ 0.00
Miscellaneous Fee:	\$ 0.00
Taxes:	\$ 0.00
One Off Discount:	\$ -(6,000.00)
QUOTE TOTALS	\$ 347,600.00

lse an 'X' to select an option below. **Quote is valid for 10 days from the	issue date. For best delivery performance, respond within 5 days.
APPROVAL & SIGNATURE REQUIRED	
Approve online by launching MyAerospace Order St this quotation.	tatus or reply directly to the email which you received
☐ Accept Quote: OVERHAUL	
Return As-Is Uncertified (Quote to be Providence)	ded)
This estimate is based on initial examinations of the unit and includes labor and material require specifications and to obtain a release tag. Honeywell reserves the right to make an adjustment to indicate approval of this estimate by signing below. Please advise immediately if any relevant Al	to this estimate based on actual material and labor costs incurred. You may
Honeywell offers OEM certified aftermarket units with one year warranty through Honeywell Aer obtain a replacement unit, purchase additional spare units, or to inquire as to your unit's value, purchase additional spare units, or to inquire as to your unit's value, purchase additional: 480-293-9751. You can also inquire online at www.aerospacetrading.com.	
Approved By:	Date:
Honeywell will proceed with repairing the equipment at the Quoted price and invoice the Custom	force between Honeywell and Customer, this quote and any services provided hereunder shall be

Lấy toàn bộ bảng bên dưới

Honeywell
THE POWER OF CONNECTED

Aei

Aerospace

Honeywell Int. SDN BHD 161 Gul Circle Singapore 629619


Quote Number : 226129716 Version 1 Custome PO: HA70762224 Part Number: 3800708-1 Validity Period: 05/26/2024 to 06/05/2024

 Sales O'der:
 552002730
 Serial In:
 P-8113
 Primary Workscope:
 OVERHAUL

 Service Order:
 5018461991
 Notification:
 349735780

BREAKDOWN

							a.			
\vdash	I tem	Part No	Part No.Out	Description	Service Bulletin	Defect Description	Qty	Unit Price	MHF	Extended Price
	001001	3094540-1		FILTER ELEM OIL			1.00	\$ 370.00	\$ 0.00	\$ 370.00
	001003	3606007-1		NUT CSTL HEX			1.00	\$ 260.00	\$ 0.00	\$ 260.00
	001004	3606009-1		NUT HEX			1.00	\$ 67.00	\$ 0.00	\$ 67.00
	001005	3830351-1		GASKET FUEL NOZ			10.00	\$ 15.60	\$ 0.00	\$ 156.00
	001006	3862624-1		GASKET PAD GEN			1.00	\$ 270.43	\$ 0.00	\$ 270.43
	001012	MS21902J4		UNION			1.00	\$ 105.35	\$ 0.00	\$ 105.35
	001019	MS9360-09		NUT			1.00	\$ 69.10	\$ 0.00	\$ 69.10
	001022	MS9489-07		BOLT			1.00	\$ 39.87	\$ 0.00	\$ 39.87
	001023	MS9489-14		BOLT			8.00	\$ 48.38	\$ 0.00	\$ 387.04
	001064	S9425-5		NUT			5.00	\$ 40.60	\$ 0.00	\$ 203.00
	001065	211-505-9001		CLAMP			1.00	\$ 20.10	\$ 0.00	\$ 20.10
	001068	234-511-9059		COUPLING CLP		Crack(s)/Cracked	1.00	\$ 154.20	\$ 0.00	\$ 154.20
	001076	AS5169D05L		FITTING, PORT PLUG			1.00	\$ 270.67	\$ 0.00	\$ 270.67
	001079	MS9489-38		BOLT			2.00	\$ 192.84	\$ 0.00	\$ 385.67
	001082	NAS1149C0563R		WASHER, FLAT			21.00	\$ 22.68	\$ 0.00	\$ 476.38
	001103	3876255-2		Pressure Sensor (LOP)			1.00	\$ 3,584.59	\$ 0.00	\$ 3,584.59
	001104	3876271-1		THERMOCOUPLE		UNABLE TO ACHIEVE REQUIRED TE	1.00	\$ 2,753.58	\$ 0.00	\$ 2,753.58
	001105	305766-4		PLUG IGNTR HV		Eroded	1.00	\$ 2,689.18	\$ 0.00	\$ 2,689.18
	001106	3617354-1		GASKET			1.00	\$ 1,105.10	\$ 0.00	\$ 1,105.10
	001107	3810794-2		GEAR SEGMENT		Chipped	1.00	\$ 324.57	\$ 0.00	\$ 324.57
	001108	3827073-7		SHIM LC BRG			1.00	\$ 89.70	\$ 0.00	\$ 89.70
	001109	3827241-1		SHIM INL HSG			2.00	\$ 534.28	\$ 0.00	\$ 1,068.55
	001110	3827608-3		SEAL AIR OIL STA		Scored/Scratched	1.00	\$ 2,190.41	\$ 0.00	\$ 2,190.41
	001111	3830418-1		SHROUD AIR FUEL NOZ		Worn	4.00	\$ 924.90	\$ 0.00	\$ 3,699.58
	001112	3840199-1		SEAL RING CURVIC		Worn	1.00	\$ 994.34	\$ 0.00	\$ 994.34





Customer PO: Sales Order:

HA70762224 552002730

Part Number:

3800708-1

Validity Period:

05/26/2024 to 06/05/2024

Service Order: 5018461991


Serial In:

P-8113

Primary Workscope: OVERHAUL Notification:

349735780

I tem	Part No	Part No.Out	Description	Service Bulletin	Defect Description	Qty	Unit Price	MHF	Extended Price
001113	3840206-2		SEAL, CURVIC			1.00	\$ 346.05	\$ 0.00	\$ 346.05
001114	3840206-3		SEAL CURVIC			1.00	\$ 339.46	\$ 0.00	\$ 339.46
001115	3844244-8		SEAL, FEATHER			12.00	\$ 66.76	\$ 0.00	\$ 801.06
001116	3844561-3		SEAL, TURB REAR BRG		Scored/Scratched	1.00	\$ 4,287.78	\$ 0.00	\$ 4,287.78
001117	3844582-2		SEAL		Grooved	1.00	\$ 1,966.56	\$ 0.00	\$ 1,966.56
001118	3844588-1		SEAL, TURBINE		Worn	1.00	\$ 2,368.53	\$ 0.00	\$ 2,368.53
001119	3844592-2		SPACER SLEEVE			8.00	\$ 52.07	\$ 0.00	\$ 416.52
001120	3844592-6		SPACER SLV			3.00	\$ 88.95	\$ 0.00	\$ 266.85
001121	3844717-1		BLANKET, INSULATION		Torn	1.00	\$ 1,755.22	\$ 0.00	\$ 1,755.22
001122	3844760-2		NOZZLE SEG TURB 1STG		Eroded	11.00	\$ 10,833.97	\$ 0.00	\$ 119,173.67
001123	3844775-1		SEAL, AIR, STATIONARY		Worn	1.00	\$ 3,859.96	\$ 0.00	\$ 3,859.96
001124	3860830-1		SEAL DISK OIL, ROTATING		Scored/Scratched	1.00	\$ 728.34	\$ 0.00	\$ 728.34
001125	3883837-1		MANIFOLD, FUEL, SECONDARY		Crack(s)/Cracked	1.00	\$ 17,295.70	\$ 0.00	\$ 17,295.70
001126	3886189-4		PACKING OIL			1.00	\$ 601.26	\$ 0.00	\$ 601.26
001127	M83413/8-G012BB		GROUNDING CABLE			1.00	\$ 31.66	\$ 0.00	\$ 31.66
001128	MS21902-6R		MS21902-6R FLAIR PER AS21902			1.00	\$ 236.72	\$ 0.00	\$ 236.72
001130	3844244-6		SEAL FEATHER			12.00	\$ 116.50	\$ 0.00	\$ 1,398.00
001131	3844573-2		RING SPRT STTR		Crack(s)/Cracked	1.00	\$ 7,891.85	\$ 0.00	\$ 7,891.85
001132	3844575-2		SHROUD SEG TURB 1STG		Eroded	9.00	\$ 1,899.86	\$ 0.00	\$ 17,098.74
001133	3844575-3		SHROUD SEGMENT		Eroded	3.00	\$ 1,851.77	\$ 0.00	\$ 5,555.31
001134	3844584-4		SHIM TURB PLENUM			1.00	\$ 234.00	\$ 0.00	\$ 234.00
001135	3844584-5		SHIM TURB PLENUM			1.00	\$ 234.00	\$ 0.00	\$ 234.00
001136	3844584-6		SHIM TURB PLENUM			2.00	\$ 166.00	\$ 0.00	\$ 332.00
001137	3844584-7		SHIM TURB PLENUM			1.00	\$ 234.00	\$ 0.00	\$ 234.00
001138	3844707-2		GASKET BRG TURB SEAL			1.00	\$ 41.53	\$ 0.00	\$ 41.53
001139	3844799-2		BOLT SPCL RING			3.00	\$ 70.07	\$ 0.00	\$ 210.21
001140	3844861-10		BLANKET		Torn	1.00	\$ 2,867.0	\$ 0.00	\$ 2,867.01
001141	3844861-6		BLANKET INSUL THERM		Torn	1.00	\$ 5,802.92	\$ 0.00	\$ 5,802.92
001142	3844861-7		BLANKET INSUL THERM		Torn	1.00	\$ 3,757.32	\$ 0.00	\$ 3,757.32





Customer PO:

HA70762224

3800708-1 Part Number:

Validity Period:

05/26/2024 to 06/05/2024

Sales Order:

552002730

P-8113

Serial In:


Primary Workscope:

OVERHAUL

Service Order: 5018461991

Notification: 349735780

I tem	Part No	Part No.Out	Description	Service Bulletin	Defect Description	Qty	Unit Price	MHF	Extended Price	
001144	S9008AK168		PIN, STRAIGHT, HEADLESS			3.00	\$ 133.0	\$ 0.0	\$ 399.0	.00
001145	3862636-1		WASHER SPR WAVE			1.00	\$ 37.7	\$ 0.0	\$ 37.7	.70
001149	3863090-1		WASHER			1.00	\$ 827.4	\$ 0.0	\$ 827.4	.44
001150	3870108-1		SPACER			5.00	\$ 78.6	\$ 0.0	\$ 393.0	.00
001151	3876237-1		GASKET TC			2.00	\$ 15.7	\$ 0.0	\$ 31.4	.40
001152	337-542-9210		FILTER ELEMENT, FLUID PRESSURE			1.00	\$ 225.0	\$ 0.0	\$ 225.0	.00
001153	370-511-9007		GROMMET			2.00	\$ 91.0	\$ 0.0	\$ 182.0	.00
001154	525-203-9008		NUT,			2.00	\$ 19.9	\$ 0.0	\$ 39.8	.80
001155	561-518-9003		SEAL			1.00	\$ 25.3	\$ 0.0	\$ 25.3	.30
001156	3827073-5		SHIM LC BRG			2.00	\$ 292.7	\$ 0.0	\$ 585.4	.48
001157	3827073-6		SHIM LC BRG			1.00	\$ 286.4	\$ 0.0	\$ 286.4	.49
001158	3827075-2		WASHER SPR CPRSN			1.00	\$ 212.0	\$ 0.0	\$ 212.0	.08
001159	3827241-2		SHIM HSG INL			1.00	\$ 534.2	7 \$ 0.0	\$ 534.2	.27
001160	3827241-3		SHIM HSG INL			1.00	\$ 569.4	2 \$ 0.0	\$ 569.4	.42
001161	3827241-4		SHIM HSG INL			1.00	\$ 1,785.4	\$ 0.0	\$ 1,785.4	.49
001162	3827405-4		ROD ACTR IGV VANES		Worn	1.00	\$ 1,226.8	5 \$ 0.0	\$ 1,226.8	.85
001163	AS1895/7-350		SEAL			1.00	\$ 56.4	5 \$ 0.0	\$ 56.4	.45
001165	145-131-9008		BOLT			3.00	\$ 17.8	\$ 0.0	\$ 53.4	.40
001166	370-511-9006		GROMMET			2.00	\$ 78.0	\$ 0.0	\$ 156.0	.00
001167	370-511-9013		GROMMET			1.00	\$ 66.6	\$ 0.0	\$ 66.6	.60
001168	370-511-9015		GROMMET			1.00	\$ 53.7	\$ 0.0	53.7	.70
001169	3827073-4		SHIM, LC BEARING			2.00	\$ 26.6	\$ 0.0	\$ 53.2	.20
001170	211-594-9214		CLAMP, PIPE, QUICK DISCONNECT			1.00	\$ 257.0	\$ 0.0	\$ 257.0	.00
001171	3863153-1		SHIM, GEARSHAFT			1.00	\$ 104.0	\$ 0.0	\$ 104.0	.00
001172	3863153-2		SHIM, GEARSHAFT			1.00	\$ 65.2	\$ 0.0	\$ 65.2	.20
001173	3863153-3		SHIM, GEARSHAFT			3.00	\$ 64.6	\$ 0.0	\$ 193.8	.80
001174	3863153-7		SHIM, GEARSHAFT			1.00	\$ 119.0	\$ 0.0	\$ 119.0	.00
001175	3863153-8		SHIM, GEARSHAFT			1.00	\$ 113.0	\$ 0.0	\$ 113.0	.00
001176	3863153-9		SHIM, GEARSHAFT			1.00	\$ 58.7	\$ 0.0	58.7	.70





Customer PO: Sales Order:

Service Order: 5018461991

HA70762224 552002730 Part Number: 3800708-1

Serial In:


P-8113

Validity Period: 05/26/2024 to 06/05/2024

Primary Workscope: OVERHAUL
Notification: 349735780

I tem	Part No	Part No.Out	Description	Service Bulletin	Defect Description	Qty	Unit Price		MHF		Extended Price	
001177	525-662-9006		NUT, SELF - LOCKING			20.00	\$	19.70	\$	0.00	\$	394.00
001178	525-662-9010		NUT, SELF - LOCKING			8.00	\$	66.00	\$	0.00	\$	528.00
001179	AS1895/7-300		SEAL, LOW PROFILE 'V' FLANGE			3.00	\$	79.87	\$	0.00	\$	239.61
001180	AS4824N06		GASKET			1.00	\$	20.30	\$	0.00	\$	20.30
001183	M83413/8-G012BC		GROUNDING CABLE			2.00	\$	41.20	\$	0.00	\$	82.40
001184	MS9386-171		PACKING PREFMD			1.00	\$	603.83	\$	0.00	\$	603.83
001185	MS9386-277		PACKING			1.00	\$	730.93	\$	0.00	\$	730.93
001186	NAS6703-9		BOLT, HEX HEAD, UNDRILLED SHANK,			1.00	\$	407.40	\$	0.00	\$	407.40
			UNDRILL									
001187	S21003-3		ID PLATE			1.00	\$	42.90	\$	0.00	\$	42.90
001189	S8990-179		PACKING, PREFORMED - SILICONE			1.00	\$	34.40	\$	0.00	\$	34.40
			RUBBER HIG									
001190	S8990-724		PACKING, PREFORMED - SILICONE			1.00	\$	31.10	\$	0.00	\$	31.10
			RUBBER HIG									
001191	3844705-2		GASKET, COVER, AFT BEARING			1.00	\$	35.20	\$	0.00	\$	35.20
001192	AA55487-3		PIN, LOCK			20.00	\$	18.88	\$	0.00	\$	377.50
001193	M2742630128D		RINGS, RETAINING, SPIRAL			1.00	\$	31.36	\$	0.00	\$	31.36
001194	M2742630129D		RINGS, RETAINING, SPIRAL			2.00	\$	17.51	\$	0.00	\$	35.01
001195	M2742630102D		RINGS, RETAINING, SPIRAL			1.00	\$	26.91	\$	0.00	\$	26.91
001196	Z1200-02		NUT			1.00	\$	196.67	\$	0.00	\$	196.67
001197	Z1200-048		NUT			1.00	\$	179.80	\$	0.00	\$	179.80
001198	3822635-3		ROTOR, SEAL		Scored/Scratched	1.00	\$	3,025.79	\$	0.00	\$	3,025.79
001199	3844738-7		SEAL, AIR, STATIONARY		Grooved	1.00	\$	6,469.51	\$	0.00	\$	6,469.51
001200	3840165-9		TURBINE ROTOR, 2ND STAGE		ERODED	1.00	\$	108,452.40	\$	0.00	\$ 1	08,452.40
001201	3840310-4		ROTOR ASSY, TURBINE - FIRST STAGE		Eroded	1.00	\$	101,930.34	\$	0.00	\$ 1	01,930.34
			AXIAL									
001202	NAS43HT3-40A		SPACER, SLEEVE			1.00	\$	65.31	\$	0.00	\$	65.31
001203	3863152-2		TUBE, TRANSFER			1.00	\$	166.44	\$	0.00	\$	166.44
001204	70723510-1		SEAL, AIR-OIL, STATIONARY			1.00	\$	3,099.79	\$	0.00	\$	3,099.79

QUOTE 226129716





Customer PO:

HA70762224

3800708-1 Part Number:

Validity Period:

05/26/2024 to 06/05/2024

Sales Order: **Service Order:** 5018461991

552002730

P-8113

Primary Workscope: Notification:


OVERHAUL 349735780

I tem	Part No	Part No.Out	Description	Service Bulletin	Defect Description	Qty	Unit Price	MHF	Extended Price
001205	70723600-1		TUBE ASSY, AIR OIL SEP BRG SUPPLY		Modified per customer request	1.00	\$ 2,415.93	\$ 0.00	\$ 2,415.93
001206	70723602-1		ADAPTER, AIR OIL SEP		CORROSION/CORRODED	1.00	\$ 8,985.16	\$ 0.00	\$ 8,985.16
001207	3870205-4		GEARSHAFT, CLUSTER, MATCHED-SET			1.00	\$ 63,177.68	\$ 0.00	\$ 63,177.68
001208	70724216-1		PACKING, PREFORMED - AMS7287			1.00	\$ 66.22	\$ 0.00	\$ 66.22
					Т	OTAL I	NEW/REPLACED PAI	RTS \$	532,429.30

Serial In:

REPA	IR/OVERHAUL	PARTS							
Item	Part No	Part No.Out	Description	Service Bulletin	Defect Description	Repair/Overhaul Description	Qty	Unit Price	Extended Price
008000	SRV2704506	2704506-5	STARTER MOTOR			Repair	1.00	\$ 0.00	\$ 0.00
008004	974710-1		SEAL, OIL		Worn		1.00	\$ 4,618.22	\$ 4,618.22
008010	2710202-1		KEY,LOCKING				1.00	\$ 226.80	\$ 226.80
008011	NAS1190E06P3K		SCREW				1.00	\$ 180.00	\$ 180.00
008014	S8454R106		LABEL HAND CRANK				1.00	\$ 113.40	\$ 113.40
008017	S8496-344		CAUTION LABEL				1.00	\$ 41.30	\$ 41.30
008018	67620906-1		BRUSH INDICATOR, ASSEMBLY		Crack(s)/Cracked		1.00	\$ 2,816.92	\$ 2,816.92
008019	67621830-2		PLATE, IDENTIFICATION				1.00	\$ 1,191.86	\$ 1,191.86
009000	SRV3888438	3888438-1	HARNESS WIRING			Repair	1.00	\$ 0.00	\$ 0.00
009001	M23053/13-002-0		INSULATION SLEEVING, HEAT				1.00	\$ 308.34	\$ 308.34
			SHRINKABLE, BL						
009002	M23053/8-006-C		INSULATION SLEEVING, HEAT				1.00	\$ 52.78	\$ 52.78
			SHRINKABLE, CL						
009005	M83723/95R1212N		CONNECTOR CONN,ROU		Worn		1.00	\$ 2,663.22	\$ 2,663.22
009006	M83723/95R12037		RECEPTACLE		Worn		2.00	\$ 2,855.15	\$ 5,710.29
009007	M83723/95R08036		CONNECTOR		Worn		1.00	\$ 1,978.77	\$ 1,978.77
009008	M83723/95R1005N		Connector		Worn		1.00	\$ 1,726.75	\$ 1,726.75
009009	M85049/52S8N		Backshell		Worn		1.00	\$ 793.55	\$ 793.55
009010	M85049/52S10N		BACKSHELL		Worn		1.00	\$ 505.53	\$ 505.53
009011	M85049/52S12N		BACKSHELL		Worn		2.00	\$ 170.34	\$ 340.68

QUOTE 226129716 Page 6 of 10





Customer PO:

HA70762224

Part Number:

3800708-1

Validity Period:

05/26/2024 to 06/05/2024

 Sales Order:
 552002730

 Service Order:
 5018461991

Serial In: P-8113

Primary Workscope:
Notification:

OVERHAUL **349735780**

Item	Part No	Part No.Out	Description	Service Bulletin	Defect Description	Repair/Overhaul Description	Qty	Unit Price	Extended Price
009012	M85049/51S12N		BACKSHELL-90 DEGREE		Worn		1.00	\$ 501.46	\$ 501.46
010000	SRV4131020	4131020-4	LUBE MODULE			Repair	1.00	\$ 0.00	\$ 0.00
010001	3880938-1		ELEMENT, OIL FILTER		100% upon Removal		2.00	\$ 1,086.56	\$ 2,173.12
010002	3881016-3		RETAINER SFT				1.00	\$ 39.70	\$ 39.70
010003	4132128-7		WASHER, SHIM .015				1.00	\$ 3,327.34	\$ 3,327.34
010004	MS16625-4068		MS16625, RING, RETAINING				1.00	\$ 30.91	\$ 30.91
010015	NAS1102E3-6		SCREW, MACH, FLH, 100 DEG, CRES,				2.00	\$ 29.75	\$ 59.49
			.190-32						
010017	MS9557-20		BOLT				5.00	\$ 199.47	\$ 997.37
010019	S3042-4		PLATE, IDENTIFICATION				1.00	\$ 135.00	\$ 135.00
010020	M2742610102D		RING-RETAINING				2.00	\$ 36.12	\$ 72.23
010021	M2742630152D		RING-RETAINING				2.00	\$ 96.67	\$ 193.34
010022	4414010		WASHER SET, SPRING TENSION				1.00	\$ 7,944.39	\$ 7,944.39
011000	SRV441921	441921-5	FUEL CONTROL AUXILIARY PWR			Repair	1.00	\$ 0.00	\$ 0.00
			UNIT,INSTL						
011001	2666850-11		PACKING,PREFORMED ROUND SECTION				1.00	\$ 58.54	\$ 58.54
011003	2670890-18		PACKING,PREFORMED RND.SECT.STR				1.00	\$ 29.47	\$ 29.47
			Т/Т ҒВ						
011004	2670890-2		PACKING,PREFORMED RND.SECT.STR				1.00	\$ 90.57	\$ 90.57
			Т/Т FB						
011005	2670890-8		PACKING,PREFORMED RND.SECT.STR				1.00	\$ 71.00	\$ 71.00
			T/T FB						
011007	2682455-006		NUT,SELF-LOCKING CAPTIVE WASHER				2.00	\$ 39.80	\$ 79.60
011010	2684752		RESOLVER AND LEVER ASSY		Under Insulation		1.00	\$ 12,337.06	\$ 12,337.06
011011	2685336		FILTER, FUEL		100% upon Removal		1.00	\$ 1,033.77	\$ 1,033.77
011012	M25988/2-036		PACKING				1.00	\$ 15.11	\$ 15.11
016000	SRV3830416	3830416-1	NOZZLE FUEL INJ			Overhaul	10.00	\$ 4,732.00	\$ 47,320.00
017000	SRV3291432	3291432-2	VALVE, LOAD CONTROL			Repair	1.00	\$ 0.00	\$ 0.00
017001	880210-3		SETSCREW	1	Broken		1.00	\$ 135.00	\$ 135.00

QUOTE 226129716



Customer PO:

HA70762224

Part Number:

Serial In:

3800708-1

Validity Period:

05/26/2024 to 06/05/2024

Sales Order:

552002730

P-8113

Primary Workscope:

OVERHAUL

Service Order: 5018461991

Notification:

349735780

Item	Part No	Part No.Out	Description	Service Bulletin	Defect Description	Repair/Overhaul Description	Qty	Unit Price	Extended Price
017004	MS21209F4-10		INSERT, HELICAL				1.00	\$ 18.81	\$ 18.81
017008	698322-10		PACKING W/RETAINER				1.00	\$ 171.30	\$ 171.30
017009	NAS1101E08H6		SCREW				2.00	\$ 19.82	\$ 39.64
017012	S8990-565		PACKING, PREFORMED - SILICONE				1.00	\$ 28.50	\$ 28.50
			RUBBER HIG						
017013	975946-2		RETAINER PIN				1.00	\$ 24.01	\$ 24.01
025000	SRV3886188	3886188-3	ACTUATOR VANE		Leaking	Overhaul	1.00	\$ 29,271.00	\$ 29,271.00
026000	SRV3876132	3876132-13	LEAD ELEC IGNTR PL			Repair	1.00	\$ 0.00	\$ 0.00
026001	230004		SEAL		Deteriorated		1.00	\$ 517.18	\$ 517.18
027000	SRV2710503	2710503-4	FIELD ASSY			Repair	1.00	\$ 508.00	\$ 508.00
027001	NAS1726C6S		NUT				1.00	\$ 16.16	\$ 16.16
031000	SRV3616140	70723947-1	FAN ASSY OIL COOLING		Inspection	Overhaul	1.00	\$ 0.00	\$ 0.00
031001	3827268-1		BELLOWS, OIL SEAL		Scored/Scratched		1.00	\$ 5,094.44	\$ 5,094.44
031002	3884703-3		RETAINER SEAL		Worn		1.00	\$ 2,456.16	\$ 2,456.16
031003	3616141-2		ROTOR FAN		Pitted		1.00	\$ 11,756.72	\$ 11,756.72
031004	3822494-1		SEAL ROT CLG FAN		Worn		1.00	\$ 1,877.88	\$ 1,877.88
031005	3822493-4		ROTOR, SEAL				1.00	\$ 4,775.11	\$ 4,775.11
033000	SRV3822666	3822666-2	BEARING		Dislodged	Repair	1.00	\$ 5,000.00	\$ 5,000.00
034000	SRV3840242	3840242-1	BEARING SET		Dented/Nicked	Repair	1.00	\$ 3,113.00	\$ 3,113.00
035000	SRV3822391	3822391-6	COMPRESSOR ROTOR		Rubbed/Abraded	Overhaul	1.00	\$ 64,497.00	\$ 64,497.00
037000	SRV3827426	3827426-4	HOUSING BRG DR CPRSR		Worn	Repair	1.00	\$ 3,720.00	\$ 3,720.00
038000	SRV3830461	3830461-6	ANNULAR COMBUSTOR CHAMBER		Worn	Repair	1.00	\$ 7,424.00	\$ 7,424.00
039000	SRV3822400	3822400-5	ROTOR COMPRESSOR		Eroded	Overhaul	1.00	\$ 1,687.00	\$ 1,687.00
040000	SRV3827504	3827504-3	CASE, ENGINE COMPRESSOR		Rubbed/Abraded	Repair	1.00	\$ 1,606.00	\$ 1,606.00
041000	SRV3616144	3616144-5	HOUSING ASSY FAN		Corrosion/Corroded	Overhaul	1.00	\$ 2,500.00	\$ 2,500.00
042000	SRV3822423	3822423-1	NUT-CPRSR BEARING		Nicked	Repair	1.00	\$ 203.00	\$ 203.00
043000	SRV3617383	3617383-1	HOUSING-FAN INLET		Corrosion/Corroded	Overhaul	1.00	\$ 610.00	\$ 610.00
044000	SRV3614588	3614588-6	RING CNTMT OCLR		Out of Round	Overhaul	1.00	\$ 1,016.00	\$ 1,016.00
044001	3614589-1		SHROUD ABRADABLE		Worn		1.00	\$ 3,116.65	\$ 3,116.65

QUOTE 226129716

Prospace

Honeywell Int. SDN BHD

161 Gul Circle Singapore 629619

Sales Order:552002730Serial In:P-8113Primary Workscope:OVERHAULService Order:5018461991Notification:349735780

Item	Part No	Part No.Out	Description	Service Bulletin	Defect Description	Repair/Overhaul Description	Qty	Unit Price	Extended Price
045000	SRV3844619	3844619-3	LINER TRNSN		Worn	Repair	1.00	\$ 752.00	\$ 752.00
046000	SRV3844917	3844917-1	RETAINER AY RLR BRG		Fretted	Repair	1.00	\$ 3,113.00	\$ 3,113.00
047000	SRV3810889	3810889-5	INLET UPPER PLENUM		Debonded / Not Adhering	Repair	1.00	\$ 305.00	\$ 305.00
048000	SRV3810919	3810919-002	DUCT		Debonded / Not Adhering	Repair	1.00	\$ 610.00	\$ 610.00
049000	SRV3810808	3810808-3	HOUSING INL		Corrosion/Corroded	Repair	1.00	\$ 752.00	\$ 752.00
049001	3810688-1		BUSHING IGV HSG		Worn		16.00	\$ 138.62	\$ 2,217.84
050000	SRV3810929	3810929-3	DUCT FAN INLET		Debonded / Not Adhering	Repair	1.00	\$ 610.00	\$ 610.00
051000	SRV3863426	3863426-5	HOUSING ASSY		Modified per customer request	Repair	1.00	\$ 3,212.00	\$ 3,212.00
051001	3863375-1		PIN BRNG ANTI-ROTATE		Worn		2.00	\$ 50.30	\$ 100.59
051002	70723601-1		FITTING, SPECIAL				1.00	\$ 1,393.81	\$ 1,393.81
052000	SRV421-529	421-529-9102	SIGHT GLASS		Worn	Repair	1.00	\$ 407.00	\$ 407.00
					-	TOTAL REPAIR/OVE	RHAU	IL PARTS \$	264,433.68

OVER & ABOVE NEW/REPLACED PARTS										
Item	Part No	Part No.Out	Description	Service Bulletin	Defect Description	Qty	Unit Price	MHF	Extended Price	
TOTAL NEW/REPLACED PARTS \$									0.00	

OVE	OVER & ABOVE REPAIR/OVERHAUL PARTS											
Item	Part No	Part No.Out	Description	Service Bulletin	Defect Description	Repair/Overhaul Description	Qty	Unit Price	Extended Price			
	TOTAL REPAIR/OVERHAUL PARTS s								0.00			

COMMENTS

The surcharge below (if any) has been added due to increases in Honeywell's global supply chain costs. For more information please go to

QUOTE 226129716 Page 9 of 10



Quote Number: 226129716 Version 1 Validity Period: Customer PO: 3800708-1 HA70762224 Part Number: 05/26/2024 to 06/05/2024 Sales Order: Serial In: **Primary Workscope:** P-8113 OVERHAUL 552002730 **Service Order:** 5018461991 Notification: 349735780

Aerospace.honeywell.com

QUOTE 226129716 Page 10 of 10