Case III Comms 1: Marshal

PILOT CALLS

F/A-18C Readback

Night (1800 - 0600 local) · Day: ceiling under 1,500 ft or visibility under 3 nm. Marshal picks the case.

MARSHAL	PADDLES (LSO)	EXAMPLE
306.300 AM	128.300 AM	BRC 275
COMM 1 CH 3 · to the deck	COMM 2 · at 3 miles	final bearing 266 · radial 086

A INSIDE 50 nm: CHECK IN WITH MARKING MOMS

SAY *Marshal, 302, marking moms 340 for 30, angels 12, state 6.5*

HEAR *302, Union Marshal, radar contact, angels 12, range 30 miles from the Abe, bearing three four zero, mother's weather ..., Case Three recovery, BRC 275, altimeter two niner niner two, marshal on the zero eight six, two one DME, angels six, expected approach time is one five, report established.*

READ BACK *302, marshal on the 086, 21 DME, angels 6, approach time 15*

- **Marking moms** is your bearing and range FROM the carrier (TACAN radial and DME).
- No reply to the readback - that is normal. Say the modex first on every call.

B AT YOUR ANGELS ON THE RADIAL: ESTABLISHED

SAY *302, established angels 6, state 6.1*

HEAR *302, Union Marshal, roger established angels six, marshal on the zero eight six, two one DME, expected approach time is one five.*

- **No Charlie in Case III.** Your approach time is your clearance to leave the stack.
- Hold on the radial: inbound leg toward the ship, turns away. Fly the shape that makes your minute.

C LOST YOUR TIME? ASK FOR IT

SAY *Marshal, 302, request push time*

HEAR *302, Union Marshal, your push time is one five.*

- **Time already gone?** Marshal gives you a new one at least 2 minutes out.
- Late in the stack by more than a few seconds - tell Marshal before you push.

D AT YOUR MINUTE: COMMENCING

SAY *302, commencing, altimeter 29.92, state 5.2*

HEAR *302, Union Marshal, copy commencing, radar contact, descend to platform five thousand, final bearing two six six, confirm BRC two seven five, report platform.*

- **Descend 4,000 fpm at 250 kts** on the final bearing. Set the final bearing on the TACAN course line.
- Continued on page 2: platform, dirty up, needles, Paddles, bolter.

THE STACK

Marshal radial = final bearing + 180. **Final bearing** = BRC - 9 (angled deck). All magnetic.

First jet: angels 6 at 21 DME. Each jet after takes the next angels up. DME = angels + 15.

Approach times are 10 minutes apart. The first is about 10 minutes after your marking moms.

"One five" = 15 minutes past the hour. Commence on the minute, inside 10 seconds.

Readbacks and "copy" get no reply. After commencing you can drop "Marshal": *302, platform* is heard. Case changes while you are in the stack: "All marshal aircraft, recovery is now Case Three, acknowledge on next push."

Case III Comms 2: Approach

PILOT CALLS

F/A-18C Readback

Night (1800 - 0600 local) · Day: ceiling under 1,500 ft or visibility under 3 nm. Marshal picks the case.

MARSHAL	PADDLES (LSO)	EXAMPLE
306.300 AM	128.300 AM	BRC 275
COMM 1 CH 3 · to the deck	COMM 2 · at 3 miles	final bearing 266 · radial 086

E PASSING 5,000 ft: PLATFORM

SAY *302, platform*

HEAR *302, Union Marshal, copy platform, final bearing two six six.*

OR SAY *302, checking in, 15 miles*

HEAR *302, Union Marshal, radar contact, 15 DME, continue.*

- **Slow to 2,000 fpm.** Level at 1,200 ft by 10 miles, on the final bearing by 12.

F 8 MILES: MARSHAL CALLS DIRTY UP

HEAR *302, Union Marshal, eight miles, dirty up.*

- **Gear, full flaps, hook.** On speed by 6 miles at 1,200 ft. No reply needed.

G NEEDLES (ACLS) - IF YOU HAVE THEM

SAY *302, needles up and left*

HEAR *302, Union Marshal, roger needles.*

OR SAY *302, negative needles*

HEAR *302, Union Marshal, roger negative needles, fly bullseye. (fly the ICLS)*

- **Coupled / command control:** "302, coupled" gets "roger coupled." Optional calls.

H 3 MILES: MARSHAL HANDS YOU TO PADDLES

HEAR *302, Union Marshal, three miles, contact paddles, call the ball.*

- **Switch COMM 2 to 128.300.** No three-mile initial call in Case III. Keep Marshal on COMM 1.

J 3/4 MILE: BALL CALL TO PADDLES

SAY *302, Hornet ball, 5.0*

HEAR *Roger ball. Then fly his calls: "a little high", "power", "right for lineup"...*

OR SAY *302, Clara, 5.0 (no ball)*

HEAR *Paddles contact, keep it coming.*

- **Trapped:** on 128.3 say "red deck", then "green deck" once clear - Paddles sends you to Deckboss.

WAVE-OFF / BOLTER · MARSHAL, COMM 1

1 Gear up, flaps half, 150 kts. Straight ahead on the final bearing, climb to 1,200 ft. Marshal calls when radar sees you go round, or say *302, bolter* / *302, wave off*
302, Union Marshal, climb to one thousand two hundred, at four miles turn downwind, report abeam.

2 At 4 miles upwind turn downwind, 2 nm offset, 1,200 ft, 150 kts. Abeam the ship say *302, abeam*
302, Union Marshal, roger abeam, four miles past abeam turn final, final bearing two six six.

3 Dirty up, turn final, intercept the final bearing. At 3 miles Marshal sends you to Paddles again - ball call as before.