

Customer Care Hotline

1-500050

PRO FORMA

Customer Name & Address

PT. Origa Mulia Fiberglass Reinforced Plastics

JI Pembangunan II RT. 001 RW. 001

Batusari, Batu Ceper Banten 15121

Tangerang
Contact:

Phone: Mobile: +6281291106344

PT. Cakrawala Automotif Rabhasa

Jl. Denpasar Raya Blok D-2 Kav 12 Jakarta Selatan 12940

Telp. : +62-21 2522292

For reference please quote the following no.						
WIP No.	Pro Forma No.	Customer No.	Page			
24669	134570	15634	1			

Regi	stration No.:	Model:		Received by:		Warrant	y/ISP Exte	nsion:
B1644PJI		GL 400 EXCLUSIVE (X1		Nurohman (Service		!		
Chassis no. / VIN:		Registration date:		Account No.: Recept		on date & time:		
WDC1668566M0053333		, ,		S0005990 28/02/2023 11.32		11.32		
_	ne no.:		ileage:	Last service dat				
	82130088721	· ·	76278	24/02/23	/ 633			
No.	Operation Nr	Description			Qty	Unit price	Disc(%)	Nett Total
1	Complaint	LAPORAN TEMUAN BENGKEL			0.00	0	0.00	0
		Bushing lower arm dan bushir	ng gardan					
6	MA166 330 01 43	BEARING BRACKET DN(154737)		1.00	6,125,200	10.00	5,512,680
7	MA166 330 02 43	BEARING BRACKET DN(154737)		1.00	6,125,200	10.00	5,512,680
10	MA166 333 06 00	ELAST. METAL BUSHING ELE D	N(154737)		1.00	386,100	10.00	347,490
8	MA166 333 08 14	ELAST. METAL BUSHING ELE D	N(154737)		1.00	479,100	10.00	431,190
9	MA166 333 09 14	ELAST. METAL BUSHING ELE D	N(154737)		1.00	479,100	10.00	431,190
2	Complaint	Bunyi "grek" dibagian depan s jalan tidak rata Follow up wio 24570	aat melewat		0.00	0	0.00	0
3	33157101	Replace 2 rear bearings on lov arm of front axle	ver transverse	control	3.50	972,000	8.00	3,129,840
4	33775002	Front final-drive unit remove/	install		4.80	972,000	8.00	4,292,352
5	33761101	Rubber bellows for two front axle shaft removed)	halfshafts repl	ace (with	1.00	972,000	8.00	894,240

Summaries	
Labor	8,316,432
Parts	12,235,230
Sublet/Sundries	0
Menus	0
Total	20,551,662
Taxes	2,260,683
Stamp	10,000
Grand Total	22.822.345

Payment made by Transfer/TT must be addressed to PT. Cakrawala Automotif Rabhasa Bank: BCA Graha Paramita Account no: 502-000-999-5, Sold item cannot be retuned.

(Company's signature & Stamp)

(Customer signature)