## HIL Limited CUSTOMER COMPLAINT INVESTIGATION AND CLOSE OUT FORM - TILES & ADHESIVE

Dated:

Complaint details:					
Complaint Tracking No:	120393		Investigation No:	74063	
Received Date:	15/03/2023	Registered Date:	16/03/2023	Attended Date:	01/04/2023
Previous Visit Date:	31/01/2023	•	Visit Date:	01/04/2023	

Name/Address of Customer	Site Address
SHINEPRO PRODUCTS(1131678)	
ZIRAKPUR,,Punjab SBU2,Punjab	

Supply Details:									
Product Code	Product Description	Invoice No	Invoice Date	Batch No	Supplied Quantity	II)efect	Actual Defect Quantity	Defect Type	Transporter
990004310	BIRLA AEROCON TILE ADHESIVE T1	2042000077	01/03/2023	111	1111	900	11	Shortage	asada
990004310	BIRLA AEROCON TILE ADHESIVE T1	2042000077	28/03/2023	111	1111	30	13	Shortage	asada
990004310	BIRLA AEROCON TILE ADHESIVE T1	2042000077	30/03/2023	111	1111	900	11	Manufacturing defects	asada
990004374	BIRLA AEROCON TILE ADHESIVE T2	2042000103	05/04/2023	111	770	30	10	Manufacturing defects	asada

Complaint Category:	Shortage
Nature of the Complaint [Provide Techinical Information]:	Trial Demo Complaint
Investigation Findings By Plant Quality:	Trial Demo

NI CO II D III OA	
Name of Quality Person : Vikas QA	Sales Represenative : vIKAS
INAME OF QUALITY FOR SOIL VIKAS QA	Sales Representive: VIKAS