## HIL Limited CUSTOMER COMPLAINT WALL PUTTY COMPENSATION REPORT

Dated:29/12/2021

Complaint Details:						
Sales Representative:	LACHICH RACTAMIALILISS LSA	-	Complaint Tracking Number :101567			
Complaint Registered Date:	02/12/2021	Complaint Attended Date:	28/12/2021			
Party Name:	Pooja Brush Manufacturing Company(1125689)	Location:	GURGAON Haryana			
Material Supplied From:		Product:	Wall Putty Manufacture/Traded			
Invoice Number and Date:	(2031010742,22/09/2021)					
Product Details:	(BIRLA HIL PUTTY-20 Kg,BIRLA HIL PUTTY-40 Kg)					

Breakage Investigation Details:								
Invoice No	Invoice Date	Product Hetalic	Supplied Quantity	Defect Quantity	Transporter	Defect %	Actual Defect Quantity	
2031010742	177/09/70171	BIRLA HIL PUTTY-20 Kg	390	1	rana Transport	0.26	1	
2031010742	177/09/70171	BIRLA HIL PUTTY-40 Kg	310	2	Rana Transport	0.65	2	
Remarks For Any Special Approvals:								

## **Compensation Recommendation:**

Based on the above inspection details, please supply to the above party (Wall Putty Manufacture/Traded) (3) numbers (in words): (THREE) or (0.1) Metric Tons of following size

Recommended Size	Recommended Quantity(No's)		
BIRLA HIL PUTTY-20 Kg	1		
BIRLA HIL PUTTY-40 Kg	2		

or issue the credit note for the above mentioned quantity of material based on the above invoice price and considering below mentioned sales recommendations.

Avinash KHATRE
QUALITY ASSURANCE
Dated:29/12/2021

Comments/Approval from Sales:

Based on the above, credit amount of .... to be issued to the above customer.

Name of the person:

Head Sales: Signature:

Any Special Remarks:

version 3 dated 14.01.12