## HIL Limited CUSTOMER COMPLAINT WALL PUTTY COMPENSATION REPORT

Dated:05/01/2022

Complaint Details:						
Sales Representative:	Vimal kumar(50003570)	Compensation Number:47585	Complaint Tracking Number :102145			
Complaint Registered Date:	22/12/2021	Complaint Attended Date:	31/12/2021			
Party Name:	direct customer, A/C Babu Ram Sood And Sons(1127966)	Location:	Sanauri Adda Punjab			
Material Supplied From:		Product:	Wall Putty Manufacture/Traded			
Invoice Number and Date:	(2031010500,31/08/2021)					
Product Details:	(BIRLA HIL PUTTY-40 Kg)					

Breakage Investigation Details:								
Invoice No	Invoice Date	Product Details	11	Defect Quantity	Transporter	Defect %	Actual Defect Quantity	
2031010500	31/08/2021	BIRLA HIL PUTTY-40 Kg	536	3		0.56	3	
Remarks For Any Special Approvals:								

## Compensation Recommendation:

Based on the above inspection details, please supply to the above party (Wall Putty Manufacture/Traded) (3) numbers (in words): (THREE) or (0.12) of following size

(THREE) of (0.12) of following size				
Recommended Size	Recommended Quantity(No's)			
BIRLA HIL PUTTY-40 Kg	3			
or issue the credit note for the above mentioned quantity of material based on the above invoice price and considering below mentioned				
sales recommendations.				

Approved By

Approved By

Avinash KHATRE

QUALITY ASSURANCE

Dated:05/01/2022

Approved By

I K PANDIT

HEAD-QUALITY ASSURANCE

Dated:05/01/2022

Comments/Approval from Sales:

Based on the above, credit amount of .... to be issued to the above customer.

Name of the person:

Head Sales: Signature:

Any Special Remarks:

version 3 dated 14.01.12