HIL Limited CUSTOMER COMPLAINT WALL PUTTY COMPENSATION REPORT

Dated:31/12/2021

Complaint Details:							
Sales Representative:	IBIRINIDERIII SINGTH BAMAHAOOO 7447		Complaint Tracking Number :101738				
Complaint Registered Date:	08/12/2021	Complaint Attended Date:	30/12/2021				
Party Name:	Parbhat Trading House(1125718)	Location:	AMRITSAR Punjab				
Material Supplied From:		Product:	Wall Putty Manufacture/Traded				
Invoice Number and Date:	(2031010588,09/09/2021)						
Product Details:	(BIRLA HIL PUTTY-20 Kg,BIRLA HIL PUTTY-40 Kg)						

Breakage Investigation Details:								
Invoice No	Invoice Date	Product Details	1.1	Defect Quantity	Transporter		Actual Defect Quantity	
2031010588	09/09/2021	BIRLA HIL PUTTY- 20 Kg	900	105	TRIP TELL TRANSPORTER	11.67	105	
2031010588	109/09/2021	BIRLA HIL PUTTY- 40 Kg	483	63	TRIL TELL TRANSPORTER	13.04	63	
Remarks For Any Special Approvals:								

Compensation Recommendation:

Based on the above inspection details, please supply to the above party (Wall Putty Manufacture/Traded) (168) numbers (in words): (ONE HUNDRED SIXTY EIGHT) or (4.62) Metric Tons of following size

Recommended Size	Recommended Quantity(No's)		
BIRLA HIL PUTTY-20 Kg	105		
BIRLA HIL PUTTY-40 Kg	63		

or issue the credit note for the above mentioned quantity of material based on the above invoice price and considering below mentioned sales recommendations.

Reviewed By Approved By I K PANDIT Avinash KHATRE HEAD-QUALITY ASSURANCE QUALITY ASSURANCE Dated:31/12/2021 Dated:31/12/2021 Comments/Approval from Sales:

Based on the above, credit amount of to be issued to the above customer.

Name of the person:

Head Sales: Signature:

Any Special Remarks:

version 3 dated 14.01.12