HIL LimitedCUSTOMER COMPLAINT COMPENSATION REPORT PIPES & FITTINGS

Dated:25/02/2019

Complaint Details:						
Sales Representative:	Giri Babu B (50002746)	Compensation	Complaint Tracking Number :53468			
Complaint Registered Date:	19/06/2018	Complaint Attended Date:	19/06/2018			
Customer Name:	DISTRIBUTOR, A/C Madhukar Electrical Co (1116817)					
Location:	Vijayawada	State:	Andhra Pradesh			
Material Supplied From:	Faridabad cPVC & uPVC Plant, Faridabad cPVC & uPVC Plant, Faridabad cPVC & uPVC Plant, Faridabad cPVC & uPVC Plant	Product:	SWR			
Compensation Mode:	Replacement Basis					

Investigation Details:							
Product Code	Product Description	Invoice No	Invoice Date	Supply Qty	Defect Qty	Actual Defect Qty	Defect Type
96000602	SWR Pipe Type A Solfit S/S 3m 75 mm	2019004816	31/03/2018	20	3	3	Other
96000604	SWR Pipe Type A Solfit S/S 3m110 mm	2019004816	31/03/2018	20	4	4	Other
96000674	SWR Pipe Type A Pushfit S/S 3m75 mm	2019004816	31/03/2018	250	18	18	Other
96000676	SWR Pipe Type A Pushfit S/S 3m110 mm	2019004816	31/03/2018	400	34	34	Other

Compensation Recommendation: Based on the above inspection details, the following size's recommended for compensation					
96000602	SWR Pipe Type A Solfit S/S 3m 75 mm	3			
96000604	SWR Pipe Type A Solfit S/S 3m 110 mm	4			
96000674	SWR Pipe Type A Pushfit S/S 3m 75 mm	18			
96000676	SWR Pipe Type A Pushfit S/S 3m 110 mm	34			

Reviewed By

Approved By

SUMAN KHUNTIA

QUALITY ASSURANCE

Dated:11/07/2018

Approved By

I K PANDIT

HEAD-QUALITY ASSURANCE

Dated:11/07/2018

Any Special Remarks: The material have been damaged due to transportation. Customer required CN against the materials.

version 3 dated 14.01.12