HIL Limited CUSTOMER COMPLAINT COMPENSATION REPORT PIPES & FITTINGS

Dated:14/04/2023

Complaint Details:						
Sales Representative:	IVIK AS(1/3456//)	-	Complaint Tracking Number :120396			
Complaint Registered Date:	13/04/2023	Complaint Attended Date:	13/04/2023			
Customer Name:	BIHARI LAL CEMENT AGENCY (1136924)					
Location:	335001	State:	Rajasthan			
Material Supplied From:	Golan Pipes and Fittings Plant, Golan Pipes and Fittings Plant	Product:	Tile Adhesive Trading			
Compensation Mode:	Credit Note					

Investigation Details:								
Product Code	Product Description	Invoice No		Supply Qty		Actual Defect Qty	Defect Type	
990005699	BIRLA HIL TA105 Floor&Wall Tile Adhesive	3403000043	08/07/2022	888	123	11	Wrong Size	
990005699	BIRLA HIL TA105 Floor&Wall Tile Adhesive	3403000034	29/06/2022	300	30	12	Wrong Size	

Compensation Recommendation:					
Based on the above inspection details, the following size's recommended for compensation					
Product Code	Product Name	Recommended Quantity(No's)			
990005699	BIRLA HIL TA105 Floor&Wall Tile Adhesive	11			
990005699	BIRLA HIL TA105 Floor&Wall Tile Adhesive	12			

Reviewed By	Approved By	
QUALITY ASSURANCE Dated:	I K PANDIT HEAD-QUALITY ASSURANCE Dated:	
Any Special Remarks:		
	ve	rsion 3 dated 14.01.12