HIL Limited CUSTOMER COMPLAINT WALL PUTTY COMPENSATION REPORT

Dated:29/12/2021

Complaint Details:								
Sales Representative:	Ashish Rastogi(50003313)	Compensation Number:47396	Complaint Tracking Number :101605					
Complaint Registered Date: 02/12/2021		Complaint Attended Date:	28/12/2021					
Party Name:	Naveen Enterprises (India)(1125568)	Location:	Gurgaon Haryana					
Material Supplied From:		Product:	Wall Putty Manufacture/Traded					
Invoice Number and Date:	(2031010509,31/08/2021)							
Product Details:	(BIRLA HIL PUTTY-20 Kg,BIRLA HIL PUTTY-1 Kg,BIRLA HIL PUTTY-5 Kg)							

Breakage Investigation Details:							
Ilnvoice No	Date	Product Details	Quantity	Defect Quantity	Transporter	Defect %	Actual Defect Quantity
2031010509	31/08/2021	BIRLA HIL PUTTY-20 Kg	210		RANA TRANSPORT	0.48	1
2031010509	31/08/20171	BIRLA HIL PUTTY-1 Kg	2000	20	RANA TRANSPORT	1	20
2031010509	31/08/2021	BIRLA HIL PUTTY-5 Kg	1600	X	RANA TRANSPORT	0.5	8
Remarks For Any Special Approvals:							

Compensation Recommendation:

Based on the above inspection details, please supply to the above party (Wall Putty Manufacture/Traded) (29) numbers (in words): (TWENTY NINE) or (0.08) Metric Tons of following size

Recommended Size	Recommended Quantity(No's)
BIRLA HIL PUTTY-20 Kg	1
BIRLA HIL PUTTY-1 Kg	20
BIRLA HIL PUTTY-5 Kg	8

or issue the credit note for the above mentioned quantity of material based on the above invoice price and considering below mentioned sales recommendations.

Reviewed By	Approved By	
Avinash KHATRE QUALITY ASSURANCE Dated:29/12/2021	I K PANDIT HEAD-QUALITY ASSURANCE Dated:29/12/2021	
Comments/Approval from Sales:		
Based on the above, credit amount of to be iss	ued to the above customer.	
Name of the person:		
Head Sales:		
Signature:		
Any Special Remarks:		
		version 3 dated 14.01.12