HIL Limited CUSTOMER COMPLAINT BREAKAGE COMPENSATION REPORT

Dated:12/01/2023

Complaint Details:							
Sales Representative:		1	Complaint Tracking Number :53502				
Complaint Registered Date:	20/06/2018	Complaint Attended Date:	28/06/2018				
Party Name:	distributor, A/C SRI VARUNA MARKETING(1121485)	Location:	Kurnool Andhra Pradesh				
Material Supplied From:		Product:	Drymix products				
Invoice Number and Date:	(9815000042,13/02/2018)						
Product Details:	(BIRLA AEROCON WALL PUTTY-1 Kg)						
Compensation Mode:	Net Loss Basis						

Breakage Investigation Details:							
Supplied Quantity (No's)	Total Breakage Quantity (No's)	Transporter	Breakages	<u> </u>	Actual Breakage Quantity In No's (after excluding 3% Breakage Qty)		
900	900	6month old material supply at the time of dispatch	100	0	900		
Remarks For Any Special Approvals:							

Compensation Recommendation:

Based on the above inspection details, please supply to the above party (Drymix products) (900) numbers (in words): (NINE HUNDRED) or (0.9) Metric Tons of following size

Recommended Size	Recommended Quantity(No's)			
BIRLA AEROCON WALL PUTTY-1 Kg	900			
an issue the smallt mate for the object mentioned growthy of material based on the above invoice union and considering below mentioned				

or issue the credit note for the above mentioned quantity of material based on the above invoice price and considering below mentioned sales recommendations.

Approved By

Approved By

I K PANDIT
HEAD-QUALITY ASSURANCE
Dated:28/06/2018

Grave at (Approved By

Comments/Approval from Sales:

Based on the above, credit amount of to be issued to the above customer.

Name of the person:

Head Sales - Panels/Blocks/Hysil/Drymix Products:

Signature:

Any Special Remarks:

version 3 dated 14.01.12