## HIL Limited CUSTOMER COMPLAINT BREAKAGE COMPENSATION REPORT

Dated:27/12/2021

Complaint Details:						
Sales Representative:	Girish Shirangannavar(50002422)	Compensation Number:47283	Complaint Tracking Number :102116			
Complaint Registered Date:	21/12/2021	Complaint Attended Date:	25/12/2021			
Party Name:	Areesh Buildtech(1121231)	Location:	BANGALORE Karnataka			
Material Supplied From:		Product:	Panel			
Invoice Number and Date:	(2008023127,16/12/2021)					
Product Details:	(Aerocon Panel (RE) 50 x 600 x 3000 MM)					

Breakage Investigation Details:								
Invoice No	Invoice Date	Product Details	Supplied Quantity	Breakage Quantity	Transporter	0/0	WITH THE NATTY I	Actual Breakage Quantity In No's (after excluding 3% Breakage Qty)
2008023127	16/12/2021	Aerocon Panel (RE) 50 x 600 x 3000 MM	220	17	SATISH ROAD	0.91	0	2
Remarks For Any Special Approvals:								

## Compensation Recommendation:

Based on the above inspection details, please supply to the above party (Panel) (2) numbers (in words): (TWO) or (0.1407) of following size

Recommended Size	Recommended Quantity(No's)		
Aerocon Panel (RE) 50 x 600 x 3000 MM	2		

or issue the credit note for the above mentioned quantity of material based on the above invoice price and considering below mentioned sales recommendations.

Reviewed By

Approved By

Avinash KHATRE
QUALITY ASSURANCE
Dated:27/12/2021

Comments/Approval from Sales:

Based on the above, credit amount of .... to be issued to the above customer.

Name of the person:
Head Sales - Panels/Blocks/Hysil/Drymix Products:
Signature:

Any Special Remarks:

version 3 dated 14.01.12